Remington Arms Co., Inc.
Product Service
Legal Case #:4982

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 212224 12/3/2010 11/4/2010 12/6/2010

Customer Information

First Name Last Name Street City State Zip Contact **Business** Type Age 4402 Angie Dr Craig Janicki Tucker GA 30084 H 770-934-3443 Incident

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4038 Could Not Duplicate Concern Unknown

S Fired on safety release Concern:1007 Fired on Safe Release

C

11/4/10 Per call from Janicki, he has had his 700 fire on safety release. He has not altered it and bought it new.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/300 RUM
 27389
 G6898999
 DD
 9/14/2009 8:12:44 PM

Date Purchased Where Purchased Accessories Original Owner

SPORTS SOUTH LLC SCOPE BASE Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

Per Ilion, replace trig assm, clean at no charge as goodwill

Repair/Replacement Repair/Replacement Cost Date

67.52


12/10/2010

11/4/10 Mailing ARS.cm 12/10/10 Per Ilion, could not duplicate concern. To restore confidence in rifle will check over, clean and replace trigger assm at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/6/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 300 RUM
	Date Code		DD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Wom; Functioning	
	Fore End Condition	Select	
n .	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.011
Sear	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
m.:	Pull	Select	4.5#
Trigger	Altered	False	
,	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SCOPE BASE



Craig of we repair Hest

4982

70 96° 4.5° 4.5°

November 4, 2010

Craig Janicki 4402 Angie Dr Tucker, GA 30084

Subject: #4982, Model 700

Dear Mr. Janicki,

Per our phone conversation, enclosed is a prepaid UPS ground shipping label for shipment of the firearm to our factory for inspection. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

enclosure

G6898999 Model: 700 RE00212224 could not deplicate consein.
To sistoil confidence in sifte
will check over jokan a suplace
TPA AT N/C
unarany

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 SPS	Serial Number: GEGA 8 999		
Are you the original owner?: VES NO			
Name: Craig Sanicki o	Date of Purchase:		
Address (no PO Boxes): 4402 Angie	Dr.		
City: Tucker	State: 34 Zip: 30094		
Phone (Daytime): 404-771-7629	Fax:		
E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be		
sent) Cjanicki 10 hotmail.co	<u> </u>		
E-mail Address:			
I would like to receive future e-mail updates from Ren	nington.		
Please describe your problem and date of occurrence:			
Weapon fires when the safety is moved from "Safe" to "Fire" without touching the triager. Problem only occurs in cold weather. the cutoff is soof or so. Will not exibit problem at room temperature.			
500 characters left			
Ammunition Information:			
Manufacturer:	Type:		
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:	Powder Weight:		
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:		



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/4/2010	REQUESTED BY:	christy
QUANTITY:	1 .	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE			
COORDINATOR			xxxxx
TO MAIL		I WILL MAIL	
DESCRIPTION:			
Λ.	Model 700		

LABEL INFORMATION

MAIL LABEL TO:	Craig Janicki 4402 Angie Dr Tucker, GA 30084		
RETURN ITEM TO	: Rem Product Service		

PRIESSE COMPLETIE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION



