Reminatori Arms Co., Inc. Product Service Legal Case #:5689

Case Information

民医学 Date Opened Date Opened(PS) **Incident Date** Pre Lit Lit Obsolete Date Closed 227600 4/1/2011 1/18/2011 4/11/2011 11/11/2010

Customer Information

Type Business First Name Last Name Street Zip Age State Incident Tam Abbas 6652 Cooper Spur Rd. Mt. Hood Parkdale OR 97041 H 541-806-6273

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

 $\mathcal{P}_{\mathcal{I}}$

PD Shot a hole in truck door

Cause: 4038 Could Not Duplicate Concern Concern: 1007 Fired on Safe Release

Unknown

5 C

Customer sent in a letter. He stated that on 11/11/10 he was hunting for buill elk. He returned to his hise around 9:30am. He put his M/700 in the passenger seat of his truck & went into house & got truck keys. He drove the truck to a gate, had some coffee & listened to the news, He noticed that his rifle was still loaded & the bolt was closed. He placed the rifle onto the console w/right arm and then released the safety w/thumb & 1st finger. The gun fired, shooting a hole through the passenger door of . truck. He stated it cost him \$2,395 to get door repaired. He feels he should be compensated for that anit & the rifle should be

Firearm Information

Mig.

Type CF/BA

Model/Ga. 700/7MM REM MA SKU

Serial Bbl.

DOM

Remington Date Furchased Where Purchased

Accessories

0/3 Original Owner

A6358425 DI 9/23/1976

BEND HOWE BEND OR SCOPE, RINGS, BASE, SCOPE COVERS

Y

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Reminatori/700/CF/8A

Release Date

Casb Reimbursement Settlement Reim. Date AFF

Cash Date APV

Repair under BLM @ n/c - goodwill gesture

Settlement

Repair/Replacement

Release of Claims

Repair/Replacement

Date

\$30.40

4/11/2011

1/18/11; Sending ARS, letter, form. df 4/8/11; Per Ilion - Could not duplicate concern. Trigger pull 2.5 lbs., set screws altered & trigger not returning properly. I called customer & we agreed to repair at n/c under BLM - goodwill gesture. We will not cover truck repairs, df

Examination[Remington/CF/BA]

		, , , , , , , , , , , , , , , , , , ,
		8.TRAVIS
;		4/4/2011
(D6)		RF
	/Dis	5 708

	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM REM MAG -
Barrei	Date Code		DI
	Sore Plugged	False	
	Buiged	False	
	Fired	Falce	
	Fired while Obstructed	**************************************	~·
	Muzzle/Crown Condition	Slightly Worn; Functioning	1
**************************************	Firing Pin	Slightly Worn; Functioning	1
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	<u></u>
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
<u> </u>	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	·
Lacking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overáli	Stock Condition	Slightly Worn; Functioning	:
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Buiged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function:	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
		Test Fired	false
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	TRIG NOT RETURNING PROPERLY
7	Pull	Select	2.5#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	94
Non-Remington Components	Description		SCOPE, RINGS, BASE, SCOPE COVERS

SL89

Tom Abbas 6652 Cooper Spur Rd. Mt. Hood Parkdale, OR 97041 Ph:

Ref: #5689

Dear Mr. Abbas,

ÅA6358425

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

Sorry I did Not send THIS SOONER, we were IN ARIZONA FOU THE WINTER 411

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 www.remington.com

TO: REMINGTON ARMS

Dec. 16, 2010

On Nov. 11, 2010 I decided to walk to the lower field in search of a bull elk. I returned to the house about 9:30 A.M. I place my Remington model 700 rifle in the passenger of my Dodge truck, barrel down, and went into the house to get my truck keys.

I drove my pick-up to the gate, overlooking the bottom field. I decided to have some coffee and listen to the news.

After a couple of minutes I noticed that my rifle still had a bullet in the chamber and the bolt was closed.

I am 61 years old and I never ever place a loaded gun in a vehicle..(except this once)

I placed the rifle onto the console with my right arm; I then released the safety with my thumb and first finger. At this moment the gun fired, shooting a hole through the passenger door of my truck. My hand was not near the trigger. I sat in shock for a minute, not believing what had just happened.

I now realized I had a bullet hole through my door and sore ribs from the kick of the gun. Thank God, no one was with me this day,

I recently got my truck out of the shop; it cost \$2395.00 to get the door repaired.

I believe I should be compensated for this amount, and my rifle should be fixed so it will never fire again, until the trigger is pulled.

I have not used it since the day it fired without pulling the trigger, and do not plan to until it is safe.

I can't sell it, knowing what I know about it, unless someone would like to buy it for testing purposes.

Thank You I wait your reply.

Tom Abbas 6652 Cooper Spur Rd. Parkdale, Or. 97756

<u>[Raset.]</u>				
Model	Sei			
Number: 700	Number: A 63	358425		
Are you the original o	wner?: 🔏YES 🗏 N	0		
Name: Ton Abbas	urchase: <i>980 Not Sur</i> <			
Address (n 6652 coper S	o PO Boxes): SPUR_Rd			
City: PARLOALE	State: OR	Zip: 97041		
Phone (Daytime): 54/-806-6073	Fax: NONE	₹		
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)				
E-mail	Address:	***************************************		
🗏 I would like to receive future	e e-mail updates from Re	mington.		
Please describe your prot	ilem and date of occum	ence:		
PLease see	Letter!			
		in the section of the		
500 c	naracters left			
Ammunition Information:				
Manufacturer: Remins toly mAG-	The same of the sa	WW Super		
Other (i.e. bullet w powder):	eight/type, shot size,			
Handload	Information:			
Powder Used:	Powder Weight:	3		
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Clear	ning and Lubrication):			

Brand of cleaning solution used: <u>の似力e3~ら</u>			
How often do you clean the bore? (Months or Number of rounds) / por yeld? - 10 rounds			
How often do you clean the action? (Months or Number of rounds) 1 per year - 10 Round S			
How often do you clean the trigger assembly? (Months or Number of rounds) 1 per year - 10 Rounds			
Brand of lubricant used: <u>04 ters Guy 0</u> iL # 445月			
How often do you lubricate the bore? (Months or Number of rounds)			
How often do you lubricate the action? (Months or Number of rounds)			
How often do you lubricate the trigger assembly? (Months or Number of rounds)			
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >ととYES 図 NO ソピルレン AGO			
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) Never - Needs かり			
What were the services performed?)			
Ship your INSURED firearm by either UPS or Parcel Post to:			
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357			
☐ WARNING : DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.			
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper			

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post, Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

TO: REMINGTON ARMS

Dec. 16, 2010

On Nov. 11, 2010 I decided to walk to the lower field in search of a bull elk. I returned to the house about 9:30 A.M. I place my Remington model 700 rifle in the passenger of my Dodge truck, barrel down, and went into the house to get my truck keys.

I drove my pick-up to the gate, overlooking the bottom field. I decided to have some coffee and listen to the news.

After a couple of minutes I noticed that my rifle still had a bullet in the chamber and the bolt was closed.

I am 61 years old and I never ever place a loaded gun in a vehicle. (except this once)

I placed the rifle onto the console with my right arm; I then released the safety with my thumb and first finger. At this moment the gun fired, shooting a hole through the passenger door of my truck. My hand was not near the trigger. I sat in shock for a minute, not believing what had just happened.

I now realized I had a bullet hole through my door and sore ribs from the kick of the gun. Thank God, no one was with me this day,

I recently got my truck out of the shop; it cost \$2395.00 to get the door repaired.

I believe I should be compensated for this amount, and my rifle should be fixed so it will never fire again, until the trigger is pulled.

I have not used it since the day it fired without pulling the trigger, and do not plan to until it is safe.

I can't sell it, knowing what I know about it, unless someone would like to buy it for testing purposes.

Thank You, I wait your reply.	JAN 10 2011
Tom Abbas	Received Date:
6652 Cooper Spur Rd. Parkdale, Or. 97756	Carana a Cada
	Response Date: Posponse/File:
	TOMOTO THE COMMENT OF THE PARTY



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		1/18/2011	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
PLEASE CHECKTONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
	Ref# 5689			
in the state of th				

LABEL INFORMATION

MAIL LABEL TO: Tom Abbas
6652 Cooper Spur Rd.
Parkdale, OR 97756—9704

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

MPLEASE/COMPLETE ALL PARTIS OF THIS FORM AND SENDATO/THE MEDIA/COORDINATOR

1 OF 1 JAN 18, 2011 ALL CURR USD ACT UT 10.0 LBS 4XX596 SVC GNOCOM TRACKING: 1/4xx5989086710718
REF 1:TOM ABBAS/CD/DMF
REF 2:5689/RIFLE HANDLING CHARGE 6.00 T/P USD SINGLE-PIECE PUS RATE CHRGS: 9.50 9.80 COD ୭୪ ଓ ୬୬୧ DGD 8.90 DC 0.00 8.82 8.80 8H 6 80 TOT PUB CHG 12.48 12.48 PUB+HANDLING









