

Remington Arms Co., Inc.
Product Service
Legal Case #:5566

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
217393	1/4/2011	1/6/2011	1/6/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bachelder	---	Bachelder	1229 Michigan Ave.	Grand Rapids	MI	49503		W 616-459-3636 F 616-459-7442

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down		Unknown	
S	Concern:1908 Fired on Bolt Closing			
C	FBC			

Dealer sent gun in for customer. Dealer stated rifled fired on close of bolt. Wants us to check safety & trigger - they froze up.
df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	25791	C6505097	DK	2/19/1990
Date Purchased	Where Purchased	Accessories	Original Owner			
	JOHNS SPORTING GOODS	MUZ BRAKE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

1/18/11: Per Ilion - Will follow down. Trigger & trigger pin rusty. Trigger binds. Replace TA, clean & test fire @ n/c. df

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

1/18/11: Per Ilion - Will follow down. Trigger & trigger pin rusty. Trigger binds. Replace TA, clean & test fire @ n/c. Gun repaired & shipped on 1/13/11. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B. TRAVIS
	Exam Date		1/6/2011

Examination	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4054	As received Follows Down	
Barrel	Description		22" 3006 SPR LH
	Date Code		DK
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ex/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG BINDS TRIG AND PIN RUSTY
	Pull	---Select---	8#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		MUZ BRAKE



1229 MICHIGAN N.E.
GRAND RAPIDS, MI 49503

22"
DEC 9/90
8th
007

DATE 12-18-19

TO: Remington

CUST. Holmgvist

ATTN Service

OUR REPAIR NO. 3725

DATE RETURNED _____

ENCLOSURE

MAKE Rm MODEL 700 CAL. 30/06 GA. _____

SERIAL # C6595097 FINISH _____ GRADE _____

BARREL _____ ACCESSORIES _____

REPAIR ORDER

- 1) Rifle fired on close of Bolt
- 2) Check safety & Trigger - they froze up.

ESTIMATE REQUEST:

- Please
☒ Only if not covered by warranty
☐ Only if charges are over \$ _____
☐ Not necessary

WE FEEL ITEM IS:

- ☐ Covered by warranty
☐ Not covered by warranty
☐ Unable to determine


BY _____

RETURN SHIPMENT TO THE ABOVE ADDRESS ONLY!!!

FOR ADDITIONAL INFORMATION REGARDING THIS ITEM, PLEASE
CONTACT LORI BACHELDER, PH: 616-459-3636, FAX: 616-459-7442

3006

C6595097
Model: 700



RE00217393

will follow down.

Trig + Trig pin rusty, Trig. BINDS.

Replace TPA clean + DET Rm.

AT H/c

A230145

