

Remington Arms Co., Inc.
Product Service
Legal Case #:5643

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
218845	1/13/2011	1/14/2011	1/14/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Lawrence	Clan	8315 Regency Woods Way	Louisville	KY	40220		H 502-499-1778 E lclan123@insightb.b.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired when he picked it up	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

1/24/11 Per letter with rifle, ab out 15 yrs ago Clan reached down to pick up his rifle and it discharged, he was with an attorney and two police officers and they thought he hit the trigger but he did not. He doubted himself but after seeing the CNBC show he realized he did not touch the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	n/a	6648150	DX	9/1/1973
Date Purchased	Where Purchased	Accessories	Original Owner			
	GILBERT SPT GD CINCIN O		Y			

CONCERN:ACCIDENTAL DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	40.00	1/24/2011				

1/24/11 Per Ilion, could not duplicate concern. Trigger assm very dirty and sticky causing part to work sluggish. Replace TPA, clean, test fire under BLSM program price of \$20 + S&H. Owner approved repair on 1/14.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/14/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		22" 308 WIN
	Date Code		DX
	Bore Plugged	False	

Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lag Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFTY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.007
	Notch	Slightly Worn; Functioning	SLUGGISH
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY, STICKY PARTS SLUGGISH
	Pull	--Select--	7.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Remington.

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 BDL ^{CUSTOM} DELUXE	Serial Number: 6648150
Are you the original owner? ☒ YES ☐ NO	
Name: LAWRENCE (LARRY) CLAN	Date of Purchase: 1974(?) (1973?)
Address (no PO Boxes): 8315 REGENCY WOODS WAY	
City: LOUISVILLE, KY	State: KY Zip: 40220
Phone (Daytime): 502-499-1778	Fax:
E-mail Address: LCLAN123@INSIGHT.B.B.COM	
☒ I would like to receive future e-mail updates from Remington.	
Please describe your problem: APP. 15 YRS AGO, REACHED DOWN TO PICK UP RIFLE AND IT DISCHARGED. I WAS WITH A COMMONWEALTH ATTY & 2 POLICEMEN AT THE TIME. THEY THOUGHT I MUST HAVE HIT THE TRIGGER, BUT I DID NOT. FOR ALL THESE YEARS I THOUGHT I MUST HAVE HIT THE TRIGGER BUT I DID NOT. I REALIZED THIS WHEN I SAW THE "REMINGTON ON FIRE" VIDEO RECENTLY. I, TOO AM A POLICE & KNOW HOW TO HANDLE A RIFLE. MY FRIENDS WERE UPSET WITH ME NEEDLESS TO SAY. THIS IS THE ONLY OCCURRENCE.	
Ammunition Information:	
Manufacturer: WINCHESTER	Type: 308 CAL
Other (i.e. bullet weight/type, shot size, powder): 308 WINCHESTER 150 GR. POWER PT. (SP)	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: HOPPE'S MOISTURE DISPLACING LUBRICANT	
How often do you clean the bore? (Months or Number of rounds) AFTER EACH USE 3-6 MONTHS IF NO USE.	
How often do you clean the action? (Months or Number of rounds) AFTER EACH USE / 5-6 mos	
How often do you clean the trigger assembly? (Months or Number of rounds) AFTER EACH USE OR 5-6 mos	
Brand of lubricant used: HOPPE'S LUBRICATING OIL	


RECEIVED
JAN 17 2011

BY:

How often do you lubricate the bore? (Months or Number of rounds)	AFTER EACH USE
How often do you lubricate the action? (Months or Number of rounds)	" " " "
How often do you lubricate the trigger assembly? (Months or Number of rounds)	" " " "
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
☐ YES ☒ NO	
Comments: THIS RIFLE HAS PROBABLY NOT BEEN FIRED MORE THAN 30-50 ROUNDS TOTAL	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? NEVER	
What were the services performed? NONE	
Ship your INSURED firearm by either UPS or Parcel Post to:	
REMINGTON ARMS CO., INC ATTN: Arms Service Division 14 Hoefler Ave Ilion, NY 13357	

6648150

Model: 700



RE00218845

YOUR FIREARM OR IN THE SAME BOX WITH THE
IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE
4E, ADDRESS (WITH ZIP CODE), TELEPHONE AND-

ig it.
nage in shipping and handling. Preferably,
returned.)
ss or damage.
the box. Shipments without a proper

it. Remington is not responsible for
urchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun).

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

could not duplicate concern.
T.R. very dirty + sticky
causing part to work sluggish.
replace TPA, clean + adjust
under BLP Low 20.00
+ ship

@note



OWNER: LAWRENCE (LARRY) CLARK
8315 REGENCY WOODS WAY
LOUISVILLE, KY 40220

PHONE 502-499-1778
RIFLE 700 BDL 308 CAL
SERIAL # 6648150

