

Remington Arms Co., Inc.
Product Service
Legal Case #:5588

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
218038	1/7/2011	1/10/2011	1/10/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Timothy	Lovern	208 Rose Lane	Port Clinton	OH	43452		C 419-341-1799

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1007 Fired on Safe Release			
C	FSR			

Customer sent gun in with our repair form. He stated that about 7 years ago the gun fired when he took the safety off. He stated he hasn't used it since. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	6580280	OW	7/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	W L BAUMLER LORAIN OH	TWO PIECE BASE	N			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Hion - Quote to repair under BLM program						

Repair/Replacement Cost	Repair/Replacement Date
\$30.40	1/30/2011

Per Hion - Will follow down. TA set screws altered. Trigger will not return properly. Replace TA, clean & test fire under BLM program - quote. df 2/1/11: I spoke w/cust. He mailed payment & appr. about a week ago. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/10/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 3006 SPR
	Date Code		OW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.004
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY T.A. DIRTY
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

5588

22"
0W 7/7
3d
004

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: 6580280
Are you the original owner? ☒ YES ☐ NO	
Name: Timothy LOVERN	Date of Purchase: WAS MY FATHER'S
Address (no PO Boxes): 208 ROSE LANE	
City: Port CLINTON	State: OHIO Zip: 43452
Phone (Daytime): 419-341-1799	Fax:
E-mail Address:	
☒ I would like to receive future e-mail updates from Remington.	
Please describe your problem: WHEN YOU GO TO TAKE SAFETY OFF IT FIRES BY ITSELF. THIS HAPPEN ABOUT SEVEN YEARS AGO AND HAVE NOT USED SENSE	
Ammunition Information:	
Manufacturer: Remington	Type: CASE LOCK
Other (i.e. bullet weight/type, shot size, powder): 180-GRAIN	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: WIPE DOWN WITH REM OIL	
How often do you clean the bore? (Months or Number of rounds) 12 months 10 ROUNDS	
How often do you clean the action? (Months or Number of rounds) 1 11	
How often do you clean the trigger assembly? (Months or Number of rounds) NEVER	
Brand of lubricant used: Rem oil	

RECEIVED
JAN 1 2011

BY:

How often do you lubricate the bore? (Months or Number of rounds)	12 MONTHS 10 ROUNDS
How often do you lubricate the action? (Months or Number of rounds)	12 MONTHS 10 ROUNDS
How often do you lubricate the trigger assembly? (Months or Number of rounds)	NEVER
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
☐ YES ☒ NO	
Comments:	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
NEVER	
What were the services performed?	
Ship your INSURED firearm by either UPS or Parcel Post to:	
REMINGTON ARMS CO., INC ATTN: Arms Service Division 14 Hoefler Ave Ilion, NY 13357	
DO NOT CLEAN, OIL OR SHOOT YOUR FIREARM OR IN THE SAME BOX WITH THE YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ADDRESS (WITH ZIP CODE), TELEPHONE AND	
Serial Number: 6580280 Model: 700	it age in shipping and handling. Preferably, returned.) s or damage. the box. Shipments without a proper Remington is not responsible for rchase insurance from your carrier. ins:
:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)	
:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.	

will follow down
 T.A. set screws altered.
 Trig will not return properly.
 replace TPA, check T28 + Pin
 under BCP for \$20.00 + ship

Quote









