

Remington Arms Co., Inc.
Product Service
Legal Case #:5347

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
215471	12/19/2010	12/7/2010	1/5/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Joseph	Mallek	3248 S. Merrill Rd	Merrill	MI	48637		H 989-643-5169 E joenbevmallek@aol.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	hole in roof of blind	Cause:4006 Altered Adjustments or Components		
S	Fired on closing bolt	Concern:1020 Fired on Bolt Opening	Unknown	
C				

12/7/10 Per email sent to Remington.com, incid #101129-000150, "I have a Remington 700-7mm Mag, Serial#6530639 that I purchased new in 1972. A few years ago while target shooting the gun discharged when I chambered a shell. At that time I thought it was a freak incident. Three years ago after shooting a deer from my blind while racking another shell in, the gun discharged, shooting a hole through the roof of my blind. That was the last time I loaded the rifle. I can no longer trust this gun not to discharge. In light of the publicity surrounding this model, it confirms my fear of using this rifle."cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM MAG	n/a	6530639		1/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAMMES GUNS BELEFONTAINE OH		Y			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	47.40	1/5/2011				

12/7/10 Mailing ARS.cm 12/30/10 Left voice message for Mallek with info on the inspection and quoted him \$37 + tax to replace trigger. Awaiting reply.cm 1/5/11 Per call from Mallek, he has approved \$37 + tax for work on the rifle.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		supry

Examination	Exam Date	12/21/2010	
	Product Type	RF	
	Action Type	A	
	Assigned To	Nagle	
Cause	4006	Altered Adjustments or Components	Trigger shoe added to trigger
Barrel	Description	26 inch with muzzle break	
	Date Code	AW	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	---Select---	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	some sticky residue
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	Model 700 Bolt Lock	
	Function	Slightly Worn; Functioning	

	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	not measured
	Notch	Slightly Worn; Functioning	
		Condition	Abused; Functioning
			Every adjustment has been altered outside of the factory, a trigger shoe was added to the trigger, t
Pull	Trigger	---Select---	2.5 lbs
Altered		True	
Sub-Assembly		M/700 Bolt Lock	
Non-Remington Components	Description		Trigger shoe, two piece scope base, scope rings, Leupold 3.5 X 10 scope, sling strap

TP - 2.5 lbs


Trigger shoe (after market)

Every adjustment screw altered
Excess oil under stock in
Receiver area
Sticky residue on bolt release.

Serial
Number

6530639

Model: 700



RE00215471

December 7, 2010

Joseph Mallek
3248 S. Merrill Rd
Merrill, MI 48637

Subject: #5347, Model 700

Dear Mr. Mallek,

Enclosed is the UPS ground prepaid shipping label for shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. **The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly.** Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator
Phone: 800-243-9700, ext 8684
christy.mitchell@remington.com

enclosure

Put in Back Rack
offer new TA under bolt lock
modification program

TRSD 12/21/10

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number:	700	Serial Number:	6530639
Are you the original owner? ☒ YES ☐ NO			
Name:	JOSEPH G. MALLER	Date of Purchase:	1972
Address (no PO Boxes): 3248 S. MERRILL RD.			
City:	MERRILL	State:	MI
		Zip:	48637
Phone (Daytime):	989 643 5169	Fax:	
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent) JOE N BEV MALLER @ AOL.COM			
E-mail Address: ☐ I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: 500 characters left			
Ammunition Information:			
Manufacturer:	HORNADAY	Type:	150GR
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	



BY _____

From: Remington Information <info@remington.com>
To: joenbevmallek <joenbevmallek@aol.com>
Subject: 700 7mmMag [Incident: 101129-000150]
Date: Wed, Dec 1, 2010 11:19 am

Recently you requested personal assistance from our on-line support center. Below is our response.

We will assume your issue has been resolved if we do not hear from you within 72 hours.

Thank you for allowing us to be of service to you.

To access your question from our support site, click here.

Subject

700 7mmMag



Discussion Thread

Response (Chris)

12/01/2010 11:19 AM

Mr. Mallek, I can send you a UPS ground prepaid shipping label to cover shipment to our factory for inspection. After inspection I would call you with the results and resolution. Let me know what address to mail the label to. That will be the address it will ship back to as well.

Customer (1 joenbevmallek@aol.com)

11/29/2010 07:26 PM

To Whom it may concern:

I have a Remington 700-7mm Mag, Serial#6530639 that I purchased new in 1972. A few years ago while target shooting the gun discharged when I chambered a shell. At that time I thought it was a freak incident. Three years ago after shooting a deer from my blind while racking another shell in, the gun discharged, shooting a hole through the roof of my blind. That was the last time I loaded the rifle. I can no longer trust this gun not to discharge. In light of the publicity surrounding this model, it confirms my fear of using this rifle. It is not safe to use.

I own several Remington firearms and I expect some direction about what to do about this issue. Please contact me at joenbevmallek@aol.com or phone 989-643-5169.

Respectfully, Joseph Mallek

Question Reference #101129-000150

Product Level 1: Firearms

Date Created: 11/29/2010 07:26 PM

Last Updated: 12/01/2010 11:19 AM

Status: Waiting


----- We hope that this information will be helpful to you. If we can be of further assistance, please contact us at 1-800-243-9700, M-F, 9am-5pm EST. Remington Arms Co. -- America's Oldest Gunmaker 870 Remington Drive, Madison, NC 27025 1-800-243-9700 or 1-336-548-8700--FAX: 1-336-548-7801 Visit us in Remington Country at <http://www.remington.com/> REMEMBER, FIREARMS SAFETY DEPENDS ON YOU! Whether you are a beginner or an advanced user, our new Safety Section is a must for everyone. <http://www.remington.com/safety> ----- [---001.001931:51103---]

Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used:	WILLIAMS
How often do you clean the bore? (Months or Number of rounds)	AFTER EACH USE
How often do you clean the action? (Months or Number of rounds)	AFTER EACH USE
How often do you clean the trigger assembly? (Months or Number of rounds)	AFTER EACH USE
Brand of lubricant used:	WILLIAMS
How often do you lubricate the bore? (Months or Number of rounds)	SAME
How often do you lubricate the action? (Months or Number of rounds)	SAME
How often do you lubricate the trigger assembly? (Months or Number of rounds)	SAME
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
☐ YES ☒ NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
NEVER	
What were the services performed?	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
⚠WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. ⚠ Record the serial number of your firearm before sending it. ⚠ Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) ⚠ Remove all accessories from your firearm to prevent loss or damage. ⚠ Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.	

Serial
Number:

6530639

Model: 700



RE00215471

JOSEPH MALLEK
2240 S. HENRIEL RD
HENRIEL, NY 14867

10 LBS


1 OF 1

RS


SHIP TO:

REMINGTON ARMS
PRODUCT SERVICES
14 MOEFLER AVE.

ILION NY 13357




NY 135 0-01



UPS GROUND

TRACKING #: 1Z 4XX 596 90 6776 1103



BILLING: 3RD PARTY
DESC: FIREARMS
RETURN SERVICE

REF 1: JOSEPH MALLEK/CD/CM
REF 2: 788

US 12.9.17

LP2432 08.06 10/2010

© 2010 UPS. All rights reserved. UPS and the UPS logo are trademarks of United Parcel Service of America, Inc. ("UPS"). All other marks are the property of their respective owners. UPS is not responsible for any loss or damage to contents. Insurance coverage is available for an additional charge. For more information, visit ups.com/insurance.

Reference #
101129-000150

Status
Solved

Assigned To
Administrators
Christy -

Product
Firearms

SLA
Not specified

Queue
CSR

700 7mmMag**Discussion Thread**

Customer (1 joenbevmailek@aol.com)

12/01/2010 07:11 PM

You can send the prepaid label to: Joseph Mailek 3248 S Merrill Road Merrill, MI 48637. I can be reached by phone at 989-643-5169. Thank you. Joe Mailek

Original Message

From: Remington Information

To: joenbevmailek

Sent: Wed, Dec 1, 2010 11:19 am

Subject: 700 7mmMag [Incident: 101129-000150]

Response (Christy -)

12/01/2010 11:19 AM

Mr. Mailek, I can send you a UPS ground prepaid shipping label to cover shipment to our factory for inspection. After inspection I would call you with the results and resolution. Let me know what address to mail the label to. That will be the address it will ship back to as well.

Date Created
11/29/2010 07:26 PM

Initial Response
12/01/2010 11:19 AM

Last Updated
12/07/2010 10:35 PM

Date Closed
12/07/2010 10:35 PM

Customer (1 joenbevmailek@aol.com)

11/29/2010 07:26 PM

To Whom it may concern:

I have a Remington 700-7mm Mag, Serial#6530639 that I purchased new in 1972. A few years ago while target shooting the gun discharged when I chambered a shell. At that time I thought it was a freak incident. Three years ago after shooting a deer from my blind while racking another shell in, the gun discharged, shooting a hole through the roof of my blind. That was the last time I loaded the rifle. I can no longer trust this gun not to discharge. In light of the publicity surrounding this model, it confirms my fear of using this rifle. It is not safe to use.

I own several Remington firearms and I expect some direction about what to do about this issue. Please contact me at joenbevmailek@aol.com or joenbevmailek@aol.com or phone 989-643-5169.

Respectfully, Joseph Mailek

Customer SmartSense
+1 (on -3 to +3 scale)

Staff SmartSense
+2 (on -3 to +3 scale)

Primary Contact

First Name: 1

Last Name: joenbevmailek@aol.com

Organization:

Login: joenbevmailek@aol.com

Title:

Contact Type:

Email: joenbevmailek@aol.com

Email - Alternate #1:

Email - Alternate #2:

Office Phone:

Mobile Phone:

Fax:

Assistant Phone:

Home Phone:

Street

City

State/Province

Postal Code

Country

Additional Information

Remington.

www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

5347

ARS LABEL REQUEST FORM

DATE:	12/7/2010	REQUESTED BY:	christy
QUANTITY:	1	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE:			
MEDIA			
COORDINATOR			
TO MAIL		I WILL MAIL	
DESCRIPTION:			
700			

LABEL INFORMATION

MAIL LABEL TO:	Joseph Mallek 3248 S Merrill Road Merrill, MI 48637
RETURN ITEM TO:	
Rem Prod Serv	

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR.

4XX596 DEC 8, 2010 ALL CURR USD 1 OF 1
SVC GND COM ACT UT 10.0 LBS
TRACKING# 124XX5969067761109
REF 1: JOSEPH MALLEK/CD/CM
REF 2: 700

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRG:
DV 0.00 CDD 0.00 SVC T/P USD
DC 0.00 DGD 0.00 RS 0.50
RH 0.00 PR 0.00 SD 0.00
TOT PUB CHG 0.20 PUB+HANDLING 0.20