

Remington Arms Co., Inc.

Product Service

Legal Case #:5384

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
218519	1/11/2011	12/10/2010	1/12/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Dalton	Meyers	5900 Rustic Dr	Uniontown	AR	72955		H 479-652-6769

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired when safety removed Concern:1007 Fired on Safe Release			
C				

12/10/10 Per call from Meyers, he has a 2nd hand 700 that recently fired when he took it off safe. It had never happened before.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06 SPR	n/a	6747854	KY	1/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
3/10/2008	SOUTHERN GUN DIST MIAMI FLA		N			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per liion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	43.69	1/18/2011				

12/10/10 Mailing ARS and box.cm 1/18/11 Meyers called and approved the repair. Per liion, could not duplicate concern.trigger assm and action very dirty and sticky.parts working sluggish.replace trigger plate assm, clean and test fire under bolt lock program for \$20.00 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/12/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		KY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.006
	Notch	Slightly Worn; Functioning	SLUGGISH
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY, STICKY
	Pull	--Select--	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

5384
December 10, 2010

Dalton Meyers
5900 Rustic Dr.
Uniontown, AR 72955

Subject: #5384, Model 700


Dear Mr. Meyers,

Thank you for your patience. Enclosed is a UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator
Phone: 800-243-9700, ext 8684
christy.mitchell@remington.com



enclosure


BY:.....

could not duplicate concern.
T.A. + act. very dirty + sticky.
parts working sluggish.
Ryhae TPA, clean + fast fire
under BLP Cor B 20.00 + ship

Quote

6747854

Model: 700



RE00218519

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 30.06		Serial Number: 6747854	
Are you the original owner? ☐ YES ☒ NO			
Name: DALTON MEYERS		Date of Purchase: 3-10-08	
Address (no PO Boxes): 5900 Rustic DR			
City: Uniontown		State: AR	Zip: 72155
Phone (Daytime): 479-652-6769		Fax:	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) dalton.meyers0000@yahoo.com			
E-mail Address:			
☐ I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence:			
I was unloading my gun after a morning hunt, as I took one bullet out of the chamber, I cycled another one in to eject it and the gun fired.			
500 characters left			
Ammunition Information:			
Manufacturer: Remington		Type: core-12k	
Other (i.e. bullet weight/type, shot size, powder): 180g. 30-6			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	

Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used:	
How often do you clean the bore? (Months or Number of rounds)	6 months
How often do you clean the action? (Months or Number of rounds)	6 months
How often do you clean the trigger assembly? (Months or Number of rounds)	6 months
Brand of lubricant used:	
How often do you lubricate the bore? (Months or Number of rounds)	6 months
How often do you lubricate the action? (Months or Number of rounds)	6 months
How often do you lubricate the trigger assembly? (Months or Number of rounds)	6 months
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
☒ YES ☐ NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
N/A	
What were the services performed?	
N/A	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.	



www.remington.com

Remington Arms Company, Inc.

870 Remington Drive

P. O. Box 700

Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	12/10/2010	REQUESTED BY:	christy
QUANTITY:	1	WEIGHT PER PACKAGE:	10
RELEASE CHECK ONE:			
MEDIA			
COORDINATOR		XXX	
TO MAIL		I WILL MAIL	
DESCRIPTION:			
700			

LABEL INFORMATION

MAIL LABEL TO:	Dalton Meyers 5900 Rustic Dr. Uniontown, AR 72955
RETURN ITEM TO:	Rem Prod Serv

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 DEC 13, 2010 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969067739509
REF 1:DALTON MEYERS/CD/CM
REF 2:700

HANDLING CHARGE 0.00		
SINGLE-PIECE PUB RATE CHRG:		SVC T/P USD
DY 0.00	COO 0.00	RS 0.00
DC 0.00	DGD 0.00	SD 0.00
AM 0.00	PR 0.00	SP 0.00
TOT PUB CHG 9.45	PUB+HANDLING	9.45

