

Remington Arms Co., Inc.
Product Service
Legal Case #:5842

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
222288	2/7/2011	2/8/2011	2/8/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Michael D. Fix Gunshop	---	Michael D. Fix	334 Mt. Penn Rd.	Reading	PA	19607		W 610-775-2067

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1007 Fired on Safe Release			
C	FSR			

Dealer sent in gun for consumer. Consumer stated gun fired on safe release. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	n/a	56637	LK	2/1/1963
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement:

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
		Remington/700/CF/BA				

Per Ilion - Quote to repair under BLM program

Repair/Replacement Cost	Repair/Replacement Date
\$62.90	2/22/2011

Per Ilion - TA set screws altered, trigger will not return properly. Replace TA, clean & test fire under BLM program - quote, 2/22/11: I called dealer & they faxed approval into Consumer Service Dept. today. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		2/8/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
		Altered Adjustments or	

3842

24" LK 2/6 2.5 1007

Michael D. Fix Gunshop, Inc.
Guns, Gunsmithing, Shooters Supplies

EFL 8-23-011-01-8H-21481
Tel (610) 775-2067

Remington.
Warranty Service
Center

334 Mt. Penn Road
Reading, Pennsylvania 19607

January 27, 2010

Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, New York 13357

Attention: Arms Service

Gentlemen:

Enclosed for service is one (1) Remington Mod. 700 ADL rifle, cal. 7 Rem. Mag., Ser. No. 56337. It was brought in to our shop with the complaint that the gun fired when the safety was removed. Please complete your safety modification.

Thank you for your continuing service and cooperation.

Sincerely,

Mike
Michael D. Fix


MDF/mlf

Enclosure

Serial Number:

56637

Model: 700



RE00222288

T.A. set screws altered, trigger
will not return properly,
replace TPA, clean & test fire
under BCP for \$20.00+ship

Quote

FEB 10 2011

BY:.....

