

Remington Arms Co., Inc.
Product Service
Legal Case #:5794

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
219479	1/18/2011	2/1/2011	2/1/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Firearms Service Ctr		Firearms Service	4754 Bardstown Rd	Louisville	KY	40218		W 502-491-5335

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fires when opening bolt	Concern:1020 Fired on Bolt Opening		
C				

2/17/11 Per note with rifle, trigger states when pulled. Trigger stops then breaks and will fire when bolt lifts.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	86223630	PA	6/2/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	K MART ENT PLYMOUTH MI	SCOPE BASE	U			

CONCRN:TRIG STOPS THEN BREAKS,FIRES WHEN BOLT LIFTS

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per lion, replace TPA, clean and test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	77.90	2/17/2011				

2/17/11 Per lion, could not duplicate concern. Trigger assm set screws altered. Can offer to replace TPA, clean and test fire at BLSM program price of \$20 + shipping. Approved by phone on 2/2.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/1/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		PA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	MIN TRIG RETURN
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE



FIREARMS SERVICE CENTER

4754 Bardstown Road
LOUISVILLE, KY 40218
(502) 491-5335

5794

22
PA6/80
35
010

CUSTOMER'S ORDER NO.		PHONE		DATE 1-11-11	
NAME Rem Arms Co					
ADDRESS					
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RET'D.
QTY	DESCRIPTION			PRICE	AMOUNT
	Rem 700 # B6223630				
	30/06				
	Trigger - Stages when pulled				
	Trigger - stops then breaks				
	+ will fire when bolt lifts				
GARY ROMAN					
TAX					
TOTAL					

10
114.90
32. —
77.90

RECEIVED
FEB 03 2011

14188

Thank You

BY:

B6223630
Model: 700

RE00219479

could not duplicate concern.
T.A. set screws altered. CAN
offer to replace TPA, clean +
test fire under BCP Ron
860.00 + ship
Quote









