

Remington Arms Co., Inc.
Product Service
Legal Case #:5761

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
220634	1/25/2011	1/26/2011	1/26/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Grundman's	---	Grundman's	75 Wildwood Ave.	Rio Dell	CA	95562		W 707-764-5744 F 707-764-2720

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C	FBC			

Dealer sent gun in for consumer. Dealer stated gun discharged when bolt closed according to consumer. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	27130	S6200589	DM	9/23/1992
Date Purchased	Where Purchased	Accessories	Original Owner			
	BILL HICKS & CO LTD	TWO PIECE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						

Repair/Replacement Cost	Repair/Replacement Date

2/11/11: Per Ilion - TA dirty & set screws altered. Replace TA, clean, & test fire @ 1/2 normal charges - quote. I faxed quote to dealer & requested contact. df 2/24/11: Spoke to Fred Grundman. He apprvd repair & pd by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/26/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	BUILT IN CUSTOM SHOP

Barrel	Description		24" 300 WIN MAG SS W/BRAKE
	Date Code		DM
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	FINISH MARRED
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		M/700 SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	MIN TRIG RETURN DEBRIS UNDER SEAR
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE



FACSIMILE TRANSMITTAL SHEET

To: Paul Date: February 11, 2011

Company: Grundman's Inc. From: Dell Fulcher

Fax No.: 707-764-2720 Fax No.: 336-548-7872

Phone No.: 707-764-5744 Phone No.: 1-800-243-9700
Press 0 and ask for ext 8686

Number of pages including Cover Sheet: 2

COMMENTS:

Please contact us concerning the following quote

PRIVILEGED AND CONFIDENTIAL

This facsimile is intended only for the use of the individual or entity to which it is addressed and may contain information that is privileged, confidential and exempt from disclosure. If you are not the intended recipient please do not disseminate, distribute, or copy this communication. Instead, please notify the sender immediately by return fax or by telephoning the number above and discard all copies of this fax.

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025-0700
Phone 336-548-8700 • www.remington.com

TRANSMISSION VERIFICATION REPORT

TIME : 02/11/2011 18:03
NAME :
FAX : 3365487823
TEL :
SER.# : BROCBJ148005

DATE, TIME
FAX NO./NAME
DURATION
PAGE(S)
RESULT
MODE

02/11 18:02
17077642720
00:00:36
02
OK
STANDARD
ECM

Remington.

FACSIMILE TRANSMITTAL SHEET

To: Paul Date: February 11, 2011

Company: Grundman's Inc. From: Dell Fulcher

Fax No.: 707-764-2720 Fax No.: 336-548-7872

Phone No.: 707-764-5744 Phone No.: 1-800-243-9700
Press 0 and ask for ext 8686

Number of pages including Cover Sheet: 2

COMMENTS:

Please contact us concerning the following quote

QUOTATION**Remington Arms Company, Inc.****ESTIMATING**Parts/Repairs:
Fax800-243-9700
336-348-7801870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

www.remington.com info@remington.com

REPORT~~ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.~~

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order Number RE00220634 Account # - R-	Description/Serial Number S6200589	Date Received - 1/25/2011 Estimate Date - 1/27/2011 Current Date - 2/11/2011
Customer GRUNDMANS INC 75 WILDWOOD AVE. RIO DELL, CA 95562 US Phone (H) (707)-764-5744 Phone (W) 		Return To GRUNDMANS INC 75 WILDWOOD AVE. RIO DELL, CA 95562 US Fax (707)-764-2720 Email

Please Circle One
 VISA MC AMEX DISCOVER Card No. _____ Exp. Date _____
 PO Number _____
 Daytime Phone (_____) _____ Time To Call _____ Open Acct. R _____
 Approval: Customer Signature _____ Date _____
☐ If You Desire Any Change Please Use The Reverse Side For Your Comments And Mark This Box
 Notice: We process checks electronically through Check 21

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTIO	M112 M123	HEADSPACE IS EXCESSIVE FORWARD TO PRODUCT SERVICE F

Technician's Comments	
Problem/Notes	trigger assm dirty and set screws altered, replace trigger plate assm, clean and test fire and bolt is binding in receiver, headspace is excessive, will fit a new bolt at 1/2 normal cost.

Estimate **C.O.D./Shipping and Handling Charges are NOT Included in this Quote							
Material #	Material Description	Qty	Warranty Y/N	Price/ Unit	Discount Percent	Extended Amt	
Part							
F27341	700 EXTRACTOR RIVET MAGNUM	1	N	\$3.20	50%	\$1.60	
F305371B	700 X-MARK PRO TRIG ASSB RH SILVER (OS	1	N	\$94.00	50%	\$47.00	
F97322	700 EXTRACTOR MAGNUM	1	N	\$12.00	50%	\$6.00	
F97701	700 SS BOLT ASSB MAG MAX F10	1	N	\$135.00	50%	\$67.50	
Service							
4000114	GR-SHIPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00	
4000119	GR-TEST	1	N	\$23.00	50%	\$11.50	
Sub Total:						\$150.60	
Est. Sales Tax:						\$7.33	
Grand Total:						\$157.93	

Guns of all Kinds
Gunsmithing

Archery

Custom Guns
our Specialty

Fishing Tackle
Sporting Goods



5761
GRUNDMAN'S INC.
"The Enthusiasts Store"

75 Wildwood Ave. • Rio Dell, California 95562
(707) 764-5744 • Fax (707) 764-2720

1-11-11

24"
DM 9/92
2.5#
012

Remington

Repair AGENT 1207

AND Remington model 700


SERIAL NO S6200589

REASON FOR SHIPMENT -

TRIGGER UNIT - GUN DISCHARGED WHEN
BOLT CLOSED ACCORDING TO CUSTOMER

RETURNED AT REMINGTONS REQUEST

THANKS




Paul Grundman BY: _____

Serial
Number:

S6200589

Model: 700



RE00220634

T.A. DIRTY & set SCREWS
ALTERED. Replace TPA, clean
+ TEST FIRE AT 1/2 NO 12 WAD
COST.

Quote

