

Remington Arms Co., Inc.
Product Service
Legal Case #:6011

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
226011	3/18/2011	3/21/2011	3/21/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Guns & Gear LLC		Guns & Gear LLC	2115 E. Lincoln Way	Cheyenne	WY	82001		W 307-632-4867 E gunsandgear@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Unintentional discharges	Concern:1025 Unexplained Discharge - No Mention of Safety Position	Unknown	
C				

3/25/11 Per note with rifle, the owner reported that he has experienced 3 unintentional discharges and requested trigger replacement.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	29747	S6287381	XP	12/27/1995
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC	TWO PIECE BASE	Y			

CONCERN: UNINTENTIONAL DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per ilion, replace TPA, clean, test fire at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

3/25/11 Per ilion, could not duplicate concern. Can offer to replace TPA, clean, test fire at 1/2 normal cost. Will test fire with slave stock and magazine.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		3/21/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 308 WIN HB SS FL
	Date Code		XP
	Bore Plugged	False	
	Ridged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Out Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	ACTION ONLY RECEIVED
	Stock Condition	---Select---	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	011
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Remington.


Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: S6287381
Are you the original owner? ☒ YES ☐ NO (OUR CUSTOMER IS)	
Name: GUNS & GEAR LLC	Date of Purchase:
Address (no PO Boxes): 2115 E. LINCOLN WAY	
City: CHEYENNE	State: WY Zip: 82001
Phone (Daytime): 307/632-4867	Fax: 307/632-3763
E-mail Address: gunsandgear@yahoo.com	
☒ I would like to receive future e-mail updates from Remington.	
Please describe your problem:	
OUR CUSTOMER, MR. FRANK RICHARDSON, REPORTS THAT HE HAS EXPERIENCED THREE (3) UNINTENTIONAL DISCHARGES AND REQUESTS TRIGGER REPLACEMENTS.	
PLEASE REFER QUESTIONS TO FRANK @ GUNS & GEAR LLC	
Ammunition Information:	
Manufacturer: N/A	Type:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used: N/A	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: N/A	
How often do you clean the bore? (Months or Number of rounds)	
of rounds)	
or Number of rounds)	
BY:	

S6287381

Model: 700



RE00226011

could not duplicate concern.
CAN offer to replace TPP, CMAP
+ TEST fire at 1/2 normal cost.

TEST w/slave steel may assist.

Quote

26"
x P12/c
4#
011

20.26
27. —
15. —
62.26

RECEIVED
MAR 23 2011