

Remington Arms Co., Inc.
Product Service
Legal Case #:5673

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
222003	2/4/2011	1/17/2011	2/17/2011	1/15/2011			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Patrick	Higney	4202 Onyx Pl.	Johnstown	CO	80534		C 970-290-4928 F 970-669-6715 E fireftph@aol.com
Incident		Charles	Higney	1484 Platte St.	Loveland	CO	80538		H 970-669-8346

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD Shot a hole in 2 trucks	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C				

1/17/11: Patrick called in & stated that his dad, Charles, was using rifle to hunt on 1/15/11 and had a FBC. Shot a hole in 2 trucks. No injury. They are both LE officers. Will send gun in for exam. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	4508	CJ	4/1/1962
Date Purchased	Where Purchased	Accessories	Original Owner			
		AFT MKT STK W/DROP OUT MAG	Y			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Remove bolt lock & replace TA @ n/c - gesture of goodwill						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$67.40	2/17/2011				

1/17/11: Sending ARS, letter, form, box. Box order# 1178244. df 2/16/11: Customer sent in pictures of truck with holes. No body shop documents, ins. docs, or repair bills. I emailed customer requesting more info. Then I will get with Danny or Fred. df 2/17/11: Customer faxed over repair bills. I spoke with Fred Roth and he stated on the rifle we would remove the bolt lock & replace the TA at n/c as goodwill gesture but we would not reimburse for the truck repairs because the set screws had been altered on the TA outside of the factory. Customer agreed to repair of rifle. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/7/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		20" 3006 SPR

	Date Code		CJ
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	O/S DOUBLE
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		AFT MKT STK W/DROP OUT MAG

5673

X [COPY]

20"
CS4/67
34
1009

January 17, 2011

Patrick & Charles Higney
4202 Onyx Pl.
Johnstown, CO 80534
Ph: 970-290-4928

Ref: # 5673

Dear Mr. Higney,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

enclosure


RECEIVED
FEB 10 2011

BY:

Serial Number:

4508

Model: 700



RE00222003

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

Print

Reset

Model Number: 700		Serial Number: 4508	
Are you the original owner? ☐ YES ☒ NO			
Name: CHARLES FREDERICK HYNES		Date of Purchase:	
Address (no PO Boxes): 4202 ENVY LN TOWNHOMES COLO 80534			
City: TOWNHOMES	State: COLO	Zip: 80534	
Phone (Daytime): (970) 290-4728		Fax: 970 669-6715	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) FIREFTPH@AOL.COM			
E-mail Address: ☐ I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: ON JAN 28 I WAS CLOSING THE BOLT ON MY RIFLE. THE BOLT PICKED UP A ROUND FROM THE MAGAZINE. I CLOSED THE BOLT AND THE WEAPON DISCHARGED. DAMAGED 2 PICKUP DECKS + GLASS. EST DAMAGE IS \$5,000.00. THIS HAS ALSO OCCURRED ON THE RANGE WHEN I WAS ON THE RANGE I CHARGED THE WEAPON AND WHEN I CLOSED THE BOLT IT FIRED - NO DAMAGE.			
500 characters left			
Ammunition Information:			
Manufacturer: REMINGTON		Type: 180	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			

Brand of cleaning solution used:	
How often do you clean the bore? (Months or Number of rounds)	After shooting
How often do you clean the action? (Months or Number of rounds)	After shooting
How often do you clean the trigger assembly? (Months or Number of rounds)	After shooting
Brand of lubricant used:	Hoppe's
How often do you lubricate the bore? (Months or Number of rounds)	After shooting
How often do you lubricate the action? (Months or Number of rounds)	After shooting
How often do you lubricate the trigger assembly? (Months or Number of rounds)	After shooting
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☐ YES ☒ NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? NEVER	
What were the services performed?)	
Ship your INSURED firearm by either UPS or Parcel Post to:	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Illon, NY 13357	
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper	

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.


Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

Please call before any Repairs
are done

970-290-4928

**CITY OF LOVELAND
POLICE DEPARTMENT**610 East Tenth Street • Suite 100 • Loveland, Colorado 80537-4942
(970) 667-2151 • Fax (970) 962-2916 • TDD (970) 663-5144
www.ci.loveland.co.us**FAX MESSAGE**

TO:

DELL FULCHER

DATE:

2-16-11

FROM:

CHUCK HIGNEY# Pages: (including cover sheet) 10 Response Requested: Yes ☐ No ☐

COMMENTS:

REF REMINGTON 5673#4642.04

Please Note: This transmittal is intended only for the addressee and may contain information that is confidential or otherwise exempt from disclosure under applicable law. If the reader is not the employee or agent responsible for delivering this message, please do not disseminate, distribute or otherwise use this information. If you have received this transmittal in error, please notify the sender.

he
reby
I. If you
ndly return

FAX # (970) 962-2916

LOVELAND POLICE DEPARTMENT



ACCREDITED 1992 - COMMISSION ON ACCREDITATION FOR LAW ENFORCEMENT AGENCIES, INC.



JD'S COLLISION REPAIR LLC

607 N. DENVER AVENUE

LOVELAND, CO 80537

OFFICE: (970)203-9888

FAX: (970)203-9889

TOLL FREE: (888)969-9888

*** SUPPLEMENT 2 ***

RO# 1547

01/10/2011 01:08 PM
S2 01/21/2011 11:46 AM

Owner

Owner: CHARLES HIGHNEY
Address: 1484 PLATTE ST
City State Zip: LOVELAND, CO 80538-4839
Home/Day: (970)669-8346
Work/Day: (970)669-8346
Control Information
Claim #: 65-8274-00401
Loss Date/Time: 01/08/2011 05:00 AM
Loss Type: Comprehensive
Deductible: None

Ins. Company: State Farm

Insured: CHARLES HIGHNEY
Home/Day: (970)669-8346

Claim Rep: Stephanie Gillingham
Work/Day: (800)324-0704

Inspection

Inspection Date: 01/10/2011 01:08 PM
Inspection Type: Select Service
Primary Impact: Right Side
Driveable: Yes
Received Date/Time: 01/11/2011 09:23 AM
Appointment Date/Time: 01/12/2011 05:00 AM

Repairer

Repairer: JD's Collision Repair LLC
Contact: Dan White L
Address: 607 North Denver Ave
City State Zip: Loveland, CO 80537

Work/Day: (970)203-9888
Home/Evening: (888)969-9888
FAX: (970)203-9889
Email: jdcollisions@qwest.net

Repair Start Date/Time: 01/17/2011
Vehicle Drop Off Date/Time: 01/17/2011 08:15 AM
Repair Complete Date/Time: 01/21/2011
Vehicle Pick Up Date/Time: 01/22/2011 10:00 AM
Target Complete Date/Time: 01/20/2011 11:33 AM
Days To Repair: 4

Vehicle

2004 Dodge Ram 250/2500 SLT 4 DR Ext Cab Short Bed
6Cyl Ho Turbo Diesel
4 Speed Automatic

2004 Dodge Ram 250/2500 SLT 4 DR Ext Cab Short Bed 01/24/2011 08:30 AM
Page 1 of 4

Claim # : 05-8274-00481 01/10/2011 01/21/2011
 Lic. Plate: 634-LON Lic State: CO
 Lic Expire: VIN: 3D7KV28C94G152440
 Prod Date: 03/2011 Mileage: 83,789
 Veh Insp# : Mileage Type: Actual
 Condition: Excellent Code: N8264A

Ext. Refinish: Two-Stage
 Ext. Color: RED
 Int. Refinish: Two-Stage

Options

4-Wheel Drive	AM/FM CD Player	Air Conditioning
Anti-lock Brakes	Auto Locking Hubs (4WD)	Center Console
Chrome Steel Wheels	Chrome Step Bumper	Cruise Control
Dual Airbags	Heated Power Mirrors	Intermittent Wipers
Keyless Entry System	Lighted Entry System	Overhead Console
Power Brakes	Power Door Locks	Power Steering
Power Take-Off Provision	Power Windows	Privacy Glass
Rear Bench Seat	Split Front Bench Seat	Tachometer
Tilt Steering Wheel	Tinted Glass	Trip Computer
Velour/Cloth Seats		

Damages

Ln#	Op	GDS	Description	MFR. Part No.	Price	AJ%	B*	MRS	R
1	N	67	Front Bumper Assy R& ADDITIONAL OPERA					0.6	SM
2	RI	42	Headlamp Assy, Hal RT R & I Assembly					0.3	SM
3	BR	104	Fender, Front RT Blend Refinish					2.1	RP
			MC 11						
			1.0 Blend						
			0.6 Two-stage setup						
			0.5 Two-stage						
4	RI	1138	Nameplate, Fender RT R & I Assembly					0.2	SM
5	I	208	Door Shell, Front RT Repair					S2 1.5*	SM
			>> DOOR SHELL MAY NEED HOLE REPAIRED. WILL ADDRESS ONCE TORN DOWN						
6	L	208	Door Shell, Front RT Refinish					3.4	RP
			2.8 Surface						
			0.6 Two-stage						
7	E	210	Pnl, Front Door Cu RT 55275856AB		260.00			6.7	SM
8	L	210	Pnl, Front Door Cu RT Refinish					0.6	RP
			0.5 Edge						
			0.1 Two-stage						
9	RI	320	Pnl, Inner Door Tr RT R & I Assembly					S1 INC	SM
10	RI	220	Mldg, Front Door S RT R & I Assembly					0.3	SM
11	E	604	W/Plate, Front Doo RT 55077331AB		47.60			0.2	SM
12	RI	475	Mirror, Outer Stan RT R & I Assembly					INC	SM
13	RI	228	Handle, Front Door RT R & I Assembly					INC	SM
14	BR	290	Pnl, Rear Door Out RT Blend Refinish					1.3	RP
			0.9 Blend						
			0.4 Two-stage						
15	RI	332	W/Strip, Belt Out RT R & I Assembly					0.2	SM
16	RI	256	Mldg, Rear Door Si RT R & I Assembly					0.3	SM
17	RI	328	Pnl, Inner Door Tr RT R & I Assembly					0.4	SM
18	RI	531	Glass, Rear Door T RT R & I Assembly					0.7	SM
19	RI	302	Channel, Rear Glas RT R & I Assembly					0.2	SM
20	RI	423	Handle, RR Door Cu RT R & I Assembly					0.8	SM
21	L	M14	Corrosion Protection Refinish					0.3*	RP
22	SB	M60	Hazardous Waste Remo Sublet Repair		5.00*				SM
			22 Items						

Claim # : 06-8274-00401 01/16/2011 01/31/2011

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$307.60
Paint Materials		\$223.30
Parts & Material Total		\$530.90
Tax on Parts & Material	@ 6.700%	\$35.57

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$48.00	10.3	2.1	12.4	\$595.20
Mech/Elec (MR)	\$80.00				
Frame (FR)	\$65.00				
Refinish (RF)	\$48.00	7.7		7.7	\$369.60
Paint Materials	\$29.00				

Labor Total	20.1	Hours	\$964.80
Sublet Repairs			\$5.00
Gross Total			\$1,536.27
Less: Deductible			None
Net Total			\$1,536.27
Rates / Taxes Adjustment			
Deductible Adjustment			
Actual Supplement Total			\$72.00
Less: Previous Net Total			\$1,464.27-
Net Supplement Total (Final Bill)			\$72.00

Alternate Parts Y/00/00/00/00/00 COM 00/00/00/00/00 Zip Code: 00000 Geo 00000
 Audatex Estimating 6.0.459 S2 01/24/2011 08:30 AM REL 6.0.459 DT
 01/01/2011 DB 01/15/2011
 Copyright (C) 2009 Audatex North America, Inc.
 2.2 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE
 REFINISH FORMULA.

*NOTICE - REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC

WELDING EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER*


THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL
 BY A STATE FARM CLAIM REPRESENTATIVE.

ESTIMATE MUST BE PRESENTED TO SHOP, ADDITIONAL CHARGES & OPEN ITEMS MUST BE
 APPROVED BY COMPANY BEFORE PAYMENT WILL BE MADE.

Op Codes

* = User-Entered Value	E = NEW PART	NG = Replace NAGS
EC = ** NON-OEM PART	ET = Partial Replace Labor	EP = ** NON-OEM PART
SU = RECYCLED PART	TE = Partial Replace Price	PM = REMAN/REBUILT PART
UM = REMAN/REBUILT PART	L = Refinish	PC = RECOND PART
UC = RECOND PART	TT = Two-Tone	SB = Sublet Repair
N = ADDITIONAL OPERATION	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	RP = RP-RELATED PRICE	

This report contains proprietary information of Audatex and may
 not be disclosed to any third party (other than the insured,
 claimant and others on a need to know basis in order to



607 N. DENVER AVE LOVELAND, CO 80537

970-283-9888

FAX 970-283-9888

EMAIL: JDS COLLISION@QWESTONET.NET

Invoice

Date	Invoice #
1/11/2011	1547

CUSTOMER INFORMATION	INSURANCE INFORMATION
CHUCK HIGNEY 1484 PLATTE ST LOVELAND, CO 80538	STATE FARM INSURANCE CLAIM #06-E274-00401

YEAR	MAKE/MODEL	VIN#	MILEAGE
2004	DOD/RAM2500	3D7KU28C94G152440	83,789

Quantity	Item Code	Description	Price Each	Amount
12.4	Body Labor	Body Labor	48.00	595.20
7.7	PAINT LABOR	PAINT LABOR	48.00	369.60
7.7	PAINT & MA...	PAINT & MATERIALS	29.00	223.30T
	HAZARDOU...	HAZARDOUS WASTE	4.99	4.99
1	PART	RIGHT FRONT DOOR OUTER PANEL 55275856AB	260.00	260.00T
1	PART	NAMEPLATE 8897331AB	47.00	47.00T
		CUSTOMER DEDUCTIBLE		
		STATE FARM TO PAY SHOP DIRECT IN THE AMOUNT OF		
		Sales Tax		
		\$1536.27	8.70%	35.58
ALL RETURNED CHECKS WILL BE CHARGED A \$35.00 PROCESSING FEE			TOTAL	\$0.00
FULL PAYMENT DUE UPON COMPLETION			CUSTOMER AMOUNT DUE	\$0.00

JD'S COLLISION REPAIR LLC

607 N. DENVER AVENUE

LOVELAND, CO 80537

OFFICE: (970)203-9888

FAX: (970)203-9889

TOLL FREE: (888)969-9888

*** SUPPLEMENT 2 ***

RO# 1548

01/10/2011 01:16 PM
82 01/31/2011 08:43 AM

Owner

Owner: DAVID COLE
Address: 2604 EUGENE DRIVE
City State Zip: LOVELAND, CO 80537
Home/Day: (970)218-4523
Work/Day: (970)218-4523
Control Information
Claim #: 06-8274-00402
Loss Date/Time: 01/08/2011 05:00 AM
Loss Type: Liability

Ins. Company: State Farm

Insured: STATE FARM INSURED

Claimant: DAVID COLE
Address: 2604 EUGENE DRIVE
City State Zip: LOVELAND, CO 80537
Home/Day: (970)218-4523

Claim Rep: Stephanie Gillingham
Work/Day: (800)324-0704

Inspection

Inspection Date: 01/10/2011 01:14 PM
Inspection Type: Select Service
Inspection Location: JDS COLLISION REPAIR
City State Zip: Loveland, CO 80537
Primary Impact: Left Side
Driveable: Yes
Received Date/Time: 01/11/2011 09:23 AM
Appointment Date/Time: 01/12/2011 05:00 AM

Orig Appraiser Name: DAN WHITE

Repairer

Repairer: JD's Collision Repair LLC
Contact: Dan White L
Address: 607 North Denver Ave
City State Zip: Loveland, CO 80537

Work/Day: (970)203-9888
Home/Evening: (888)969-9888
FAX: (970)203-9889
Email: jdscollision@qwest.net

Repair Start Date/Time: 01/24/2011
Vehicle Drop Off Date/Time: 01/24/2011 07:45 AM
Repair Complete Date/Time: 01/28/2011
Vehicle Pick Up Date/Time: 01/28/2011 10:55 AM
Target Complete Date/Time: 01/28/2011

1999 Ford F-250 Super Duty XLT 4 DR Ext Cab Long Bed 01/31/2011 08:43 AM
Page 1 of 4

Claim # : 06-8274-80402 01/10/2011 01/31/2011
Days To Repair: 5

Vehicle

1999 Ford F-250 Super Duty XLT 4 DR Ext Cab Long Bed
8cyl Diesel Turbo 7.3L
4 Speed Automatic

Lic. Plate: 624-LON Lic State: CO
Lic Expire: VIN: 1FTNE21F6XED48012
Prod Date: 02/1999 Mileage: 119,544
Veh Insp# : Mileage Type: Actual
Condition: Excellent Code: P8185A

Ext. Refinish: Two-Stage
Ext. Color: WHITE
Int. Refinish: Two-Stage

Options

4-Wheel Drive AM/FM Stereo Tape Airbag Restraint
Anti-Lock Rear Brakes Intermittent Wipers Leather Steering Wheel
Manual Locking Hubs Power Brakes Power Steering
Tachometer Velour/Cloth Seats

Damages

Ln#	Op	GDE	Description	MFR. Part No.	Price	AJ*	B*	HRS	R
1	N	13	Front Bumper Assy	R& ADDITIONAL OPERA				0.5	SM
2	BR	103	Fender, Front	LT Blend Refinish				2.1	RF
				MC 13					
				1.0 Blend					
				0.6 Two-stage setup					
				0.5 Two-stage					
3	RI	110	Nameplate, Fender	LT R & I Assembly				0.2	SM
4	RI	885	Seat Assembly, Dri	LT R & I Assembly			\$1	0.4	SM
5	RI	886	Seat Assembly, Pas	RT R & I Assembly			\$1	0.4	SM
6	I	207	Door Shell, Front	LT Repair			\$1	1.5*	SM
			>> DOOR SHELL MAY NEED REPAIRED. WILL TEAR DOWN AND ADVISE						
7	L	207	Door Shell, Front	LT Refinish				2.6	RF
				2.2 Surface					
				0.4 Two-stage					
8	R	209	Pnl, Front Door Ou	LT 8C3E2520201A	479.38			7.6	SM
9	L	209	Pnl, Front Door Ou	LT Refinish				0.6	RF
				0.5 Edge					
				0.1 Two-stage					
10	RI	205	W/Strip, Belt Oute	LT R & I Assembly				INC	SM
11	R	233	Pnl, Inner Door Tr	LT P81E2523943AAA	252.73*		\$1	0.1	SM
				MC #					
# = 01, 02									
			>> PRICED THRU DEALER						
12	RI	255	Mldg, Front Door L	LT R & I Assembly				0.3	SM
13	RI	316	N/Plate, Front Doo	LT R & I Assembly				0.2	SM
14	RI	269	Mirror, Outer Stan	LT R & I Assembly				INC	SM
15	RI	215	Glass, Front Door	LT R & I Assembly			\$1	INC	SM
16	RI	486	Channel, Front Gla	LT R & I Assembly				INC	SM
17	RI	249	Handle, Front Door	LT R & I Assembly				INC	SM
18	BR	289	Pnl, Rear Door Out	LT Blend Refinish				1.3	RF
				0.9 Blend					
				0.4 Two-stage					
19	RI	346	Mldg, Rear Door Lo	LT R & I Assembly				0.3	SM
20	RI	312	Pnl, Inner Door Tr	LT R & I Assembly				0.8	SM

1999 Ford F-250 Super Duty XLT 4 DR Ext Cab Long Bed 01/31/2011 08:43 AM
Page 2 of 4

Claim # : 06-8274-00402 01/10/2011 01/31/2011

21 RI	310 Mldg, Inner Door T LT R & I Assembly		INC	SM
22 L	M14 Corrosion Protection Refinish		0.3*	RF
23 SB	M60 Hazardous Waste Remo Sublet Repair	5.00*		SM
24 E	LT FRONT SEAT CUSION NEW PART	98.18*		SM*
25 E	RT FRONT SEAT CUSION NEW PART	98.02*		SM*
26 E	CENTER FRONT SEAT CU NEW PART	125.73*		SM*
27 SB	RECOVER FRONT SEAT Sublet Repair	785.00*	S1	SM*
	>> RECOVER FRONT SEATS AND CENTER SEAT WITH NEW SEAT COVERS AND INSALL			
	>> OF SEAT CUSIONS.			
	>> WORK COMPLETED BY UNIVERSITY UPHOLSTERY			
28 N	CLEAN AND RETAPE ADDITIONAL OPERA	7.50*	S1 1.0*	SM*
	>> TIME IS FOR 2 SIDE DOOR MLDGS AND 2 NAMEPLATES			
28 Items				

MC Message

01 CALL DEALER FOR EXACT PART # / PRICE
02 PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO.
13 INCLUDES 0.5 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$1,054.04
Other Parts		\$7.50
Paint Materials		\$200.10
Parts & Material Total		\$1,261.64
Tax on Parts & Material	@ 6.700%	\$84.53

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$48.00	10.3	3.0	13.3	\$638.40
Mech/Elec (ME)	\$80.00				
Frame (FR)	\$65.00				
Refinish (RF)	\$48.00	6.9		6.9	\$331.20
Paint Materials	\$29.00				

Labor Total	20.2	Hours	\$969.60
Sublet Repairs			\$790.00
Gross Total			\$3,105.77
Net Total			\$3,105.77
Rates / Taxes Adjustment			
Deductible Adjustment			
Less: Previous Net Total			\$3,105.77-
Net Supplement Total (Final Bill)			\$0.00

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 00000 Geo 00000
Audatex Estimating 6.0.459 S2 01/31/2011 08:43 AM REL 6.0.459 DT
01/01/2011 DB 01/15/2011
Copyright (C) 2009 Audatex North America, Inc.
2.0 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE
REFINISH FORMULA.

*NOTICE - REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC

WELDING EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER*

THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL
BY A STATE FARM CLAIM REPRESENTATIVE.

ESTIMATE MUST BE PRESENTED TO SHOP, ADDITIONAL CHARGES & OPEN ITEMS MUST BE

1999 Ford F-250 Super Duty XLT 4 DR Ext Cab Long Bed 01/31/2011 08:43 AM
Page 3 of 4


Claim # : 06-8274-00402 01/10/2011 01/31/2011
APPROVED BY COMPANY BEFORE PAYMENT WILL BE MADE.

Op Codes

* = User-Entered Value	E = NEW PART	NG = Replace NAGS
EC = ** NON-OEM PART	ET = Partial Replace Labo	EP = ** NON-OEM PART
EU = RECYCLED PART	TE = Partial Replace Pric	PM = REMAN/REBUILT PART
UM = REMAN/REBUILT PART	L = Refinish	PC = RECOND PART
UC = RECOND PART	TT = Two-Tone	SB = Sublet Repair
N = ADDITIONAL OPERATION	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	RP = RP-RELATED PRIOR	

This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2009 Audatex North America, Inc.



COLLISION REPAIR, LLC

607 N. DENVER AVE LOVELAND, CO 80537

978-2-213-23232-2

FAX 978-283-9999

EMAIL: IDSCOLLISION@WESTOF.EMET

Invoice

Date	Invoice #
1/11/2011	1548

CUSTOMER INFORMATION DAVE COLE 2604 EUGENE LOVELAND, CO 80537	INSURANCE INFORMATION STATE FARM INSURANCE CLAIM #06-8274-00462
--	--


YEAR	MAKE/MODEL	VIN#	MILEAGE
1999	FORD/F-250	1FTNX21F8XED40012	119,544


Quantity	Item Code	Description	Price Each	Amount
13.3	Body Labor	Body Labor	48.00	638.40
6.9	PAINT LABOR	PAINT LABOR	48.00	331.20
8.9	PAINT & MA...	PAINT & MATERIALS	28.00	200.10
	HAZARDOU...	HAZARDOUS WASTE	5.00	5.00
1	PART	LEFT FRONT DOOR OUTER PANEL 0C8Z2520201A	479.38	479.38
1	PART	LEFT INNER DOOR TRIM PANEL F81Z25239480AC	252.73	252.73
1	PART	SEAT PAD F81Z25632A23DA	98.18	98.18
1	PART	SEAT PAD F81Z25632A22DA	98.02	98.02
1	PART	SEAT PAD 7C3Z25632A22A	125.73	125.73
1	SUBLET	RECOVER TWO FRONT SEATS AND CENTER JUMP SEAT	785.00	785.00
	SHOP SUPP...	DOUBLE SIDED TAPE	7.50	7.50
		STATE FARM TO PAY SHOP DIRECT IN THE AMOUNT OF Sales Tax	\$3105.77 6.70%	84.53

FULL PAYMENT DUE UPON COMPLETION


CUSTOMER AMOUNT DUE \$0.00



















www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	1/17/2011	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PKG:	10 lbs
☐ RELEASE CHECK ONE			
MEDIA COORDINATOR TO MAIL		I WILL MAIL	XXXXXX
DESCRIPTION: Ref # 5673 rifle			

LABEL INFORMATION

MAIL LABEL TO: Patrick & Charles Higney 4202 Onyx Pl. Johnstown, CO 80534 Ph: 970-290-4928
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX586 JAN 18, 2011 ALL CURR USD 1 OF 1
SVC CNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5869065873617
REF 1: PATRICK/CHARLES HIGNEY/CD/DMF
REF 2: 5673/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRG: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AM 0.00 PR 0.00 SP 0.00
TOT PUB CHG 11.23 PUB+HANDLING 11.23

