

Remington Arms Co., Inc.
Product Service
Legal Case #:5663

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
219196	1/14/2011	1/17/2011	1/17/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Hilltop Hunting	---	Hilltop Hunting	374 Pollock Rd.	Canton	NY	13617		W 315-386-4875

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1007 Fired on Safe Release			
C	FSR			

Dealer sent gun in for consumer. Their paperwork stated Customer claims unintentional discharge upon movement of safety.
df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	25777	B6450966	CD	4/1/1983
Date Purchased	Where Purchased	Accessories	Original Owner			
	WESTERN WHLSE DENVER COLO	SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$47.40	2/4/2011				

2/4/11: Per Ilion - Could not duplicate concern. Safe works hard at times. Replace TA, clean & test fire at n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/17/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM REM MAG

Barrel	Date Code		CD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		M/700 SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	SOME LITE RUST ON TRIG SAFETY WORKS HARD AT TIMES
	Pull	---Select---	5#
	Altered	False	SEALANT MISSING
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

HILLTOP HUNTING & FISHING SUPPLY

374 Pollock Road Canton, NY 13617

(315) 386-4876

JOE RUSSELL - GUNSMITH

"The Gun Doctor"

www.hilltopguns.com

24"
CD 4/83
5
1011

5663

1/6/11

CUSTOMER'S ORDER NO. PHONE DATE

NAME Rem:

ADDRESS

SOLD BY CASH C.O.D. CHARGE ON ACCT. MOSE. RETD. PAID OUT

DESCRIPTION PRICE AMOUNT

Customer Claims						
UNintentional Discharge						
upon movement of						
safety.						
please check						
+ repair						
RECEIVED BY		TAX				
		TOTAL				


RECEIVED
JAN 19 2011

BY: _____

THANK YOU

B6450966

Model: 700



RE00219196

could not duplicate concern.
S&L works hard at times,
replace T&A, clean + test fire
AT H/L

230145

