

Remington Arms Co., Inc.
Product Service
Legal Case #:5741

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
220052	1/21/2011	1/24/2011	1/24/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Donald	Sines	3433 Lazzelle Union Rd.	Morgantown	WV	26501		H 304-328-5486 E davidsines@hotmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Customer sent gun in with our repair form. He stated that gun shoots when releasing safety. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	6515344	LW	2/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	M W DIST CHARLESTON W VA		Y			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM	Repair/Replacement Cost \$30.40	Repair/Replacement Date 2/7/2011				

Per Ilion - Could not duplicate concern. TA dirty & rusty, sear works sluggish. Replace TA, clean & test fire under BLM - quote. Customer approved & pd by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/24/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		LW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	009
	Notch	Slightly Worn; Functioning	SLUGGISH
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY, RUSTY SEAR WORKS SLUGGISH
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: 6515344
Are you the original owner? ☒ YES ☐ NO	
Name: DONALD SINES	Date of Purchase: 1975 ?
Address (no PO Boxes): 3433 LAZZELLE UNION RD MORGANTOWN WV 26501	
City: MORGANTOWN, WV	State: WV Zip: 26501
Phone (Daytime): 304-328-5486	Fax:
E-mail Address: DAVID SINES @HOTMAIL.COM	
☒ I would like to receive future e-mail updates from Remington.	
Please describe your problem:	
SHOTS WHEN PULLING SAFETY	
- BOTH WAYS	
• TO UNLOCK BOLT	
• TO RELEASE BEFORE SHOOTING	
NEVER TAMPERED WITH TRIGGER MECHANISM - BUILT NEW -	
MAYBE USED GUN - SHOT 10 TIMES	
Ammunition Information:	
Manufacturer:	Type:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used:	
How often do you clean the bore? (Months or Number of rounds)	
How often do you clean the action? (Months or Number of rounds)	
How often do you clean the trigger assembly? (Months or Number of rounds)	
Brand of lubricant used:	

RECEIVED
JAN 25 2011

* SHIPPED WITH BOLT OUT *


ALTERNATE NUMBER - 703-851-2795 - MY SON
DAVID SINES HELPING ME

How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? ☐ YES ☐ NO
Comments:
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? <i>N/A</i>
What were the services performed? <i>N/A</i>
Ship your INSURED firearm by either UPS or Parcel Post to:
REMINGTON ARMS CO., INC ATTN: Arms Service Division 14 Hoefler Ave Ilion, NY 13357
ⓈWARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE INCLUDE THE ADDRESS (WITH ZIP CODE), TELEPHONE AND E-MAIL ADDRESS OF THE PERSON TO WHOM THE SHELLS ARE BEING SENT. Damage in shipping and handling. Preferably, (if returned) no loss or damage. In the box. Shipments without a proper label. Remington is not responsible for loss or damage. Purchase insurance from your carrier. Deliveries: • Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun) • For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

Serial Number:

6515344

Model: 700



RE00220052

*could not duplicate concern.
 T.A. dirty & rusty, SEAR WORKS
 sluggish. Replaced TPA, cleaned.
 TEST FIRE under BLP Ron
 \$ 20.00 + ship
 Quote*

