

Remington Arms Co., Inc.
Product Service
Legal Case #5923

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
224016	2/22/2011	2/23/2011	2/23/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Scheels Sports		Scheels Sports	1375-A S Columbia Rd	Grand Forks	ND	58201		W 701-780-9424
Incident		Rodney	Skadsen						H 701-350-0013

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fires on safety release	Cause:4006 Concern:1007	Altered Adjustments or Components Fired on Safe Release	Unknown
C				

3/8/11 Per note with firearm, gun goes off when switching safety from safe to fire.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Rhl.	DOM
Remington	CF/BA	700/243 WIN	26905	T6220274	PQ	6/10/1996
Date Purchased	Where Purchased	Accessories	Original Owner			
	ZANDERS SPORTING GOODS * GLEN	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				
	47.26	3/8/2011				

3/8/11 Per Ilion, trigger assm set screws altered. Trigger has no return. Replace TPA, clean, test fire at 1/2 normal cost.cm
3/10/11 Mike at Scheels approved.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/23/2011
	Product Type		RF

	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 243 WIN SS
	Date Code		PQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.013
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	NO TRIG RETURN
	Pull	---Select---	1.75#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

SHEELS SPORTS
1375-A South Columbia Road
GRAND FORKS, NORTH DAKOTA 58201

RETURN TO VENDOR

32263 24
806/1
1.73

(701) 780-9424

Remington Arms

DATE <u>2/16/11</u>	OUR P.O. NO.
AUTHORIZATION NO.	PERSON AUTHORIZING RETURN
HOW RETURNED <u>UPS</u>	SHIPPING CHARGES ☐ PREPAID ☐ COLLECT

QTY RETD.	YOUR INVOICE NO.	STOCK NUMBER	DESCRIPTION	UNIT PRICE	TOTAL AMOUNT
1			Remington 700 243		
			Sn# T6220274		
			gun goes off when switching safety from safe to fire		

REASON FOR RETURN	ACTION REQUESTED
☐ OVERSTOCK	☒ REPAIR AND RETURN @ NO CHARGE
☐ OVERSHIPMENT ON P.O. #	☐ REPAIR AND BILL
☐ SUBSTITUTION ON P.O. #	☐ REPLACE @ NO CHARGE
☒ DEFECTIVE (EXPLAIN)	☐ ISSUE FULL CREDIT
	☐ OTHER

REPAIR TAG




2/16/11
DATE PROMISED

DATE RECEIVED	42075
CUSTOMER <u>Rodney Skadsen</u>	
ADDRESS <u>1212 1st St</u>	
CITY, STATE <u>Grand Forks ND 58201</u>	PHONE

RETURNING COMPANY CONTACT: L. Chesher

T6220274

Model: **700**



RE00224016

- Send to Remington	
- Gun goes off	
when safety is switched	
from safe to fire	
Serial #	
T6220274	
DATE WORK COMPLETED	TOTAL

T.A. set screws altered,
trigger has no return. Replace
TPA, clean & test like at
1/2 normal cost.

Quote

27
20.26
47.26

RECEIVED
FEB 25 2011

BY:



