

Remington Arms Co., Inc.
Product Service
Legal Case #6070

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
227320	3/30/2011	3/31/2011	3/31/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Scott's Gunsmithing & Sales LLC		Scott's Gunsmith	4201 South US Hwy 441	Lake City	FL	32025		W 386-752-9898

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S Discharges when safety released	Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release		Unknown	
C				
4/11/11 Per note with rifle, "discharges when safety released, recall?" .cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	B6216019	KA	5/14/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	K MART ENT FAIRLESS HILLS PA	SLING	U			

CONCERN:FSR, RECALL

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at BLSM price						
	Repair/Replacement Cost	Repair/Replacement Date				
	38.40	4/11/2011				

4/11/11 Per Ilion, could not duplicate concern. Can offer to replace TPA, clean and test fire under BLSM program for \$20 + S&H.cm 4/28/11 Emailed quote/inspect info.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/31/2011
	Product Type		RF

	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		KA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	013
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	6.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SLING

Federal Firearms License
(18 U.S.C. Chapter 44)

In accordance with the provisions of Title I, Gun Control Act of 1968, and the regulations issued thereunder (27 CFR Part 478), you are licensed to engage in the business specified in this license, within the limitations of Chapter 44, Title 18, United States Code, and the regulations issued thereunder, until the expiration date shown. See "WARNINGS" and "NOTICES" on reverse.

Direct ATF ATF - Chief, FFLC
Correspondence To 244 Needy Road
 Martinsburg, WV 25405-9431

License
Number **1-59-023-01-3G-06566**

Chief, Federal Firearms Licensing Center (FFLC)

Expiration
Date **July 1, 2013**

Name
SCOTTS GUNSMITHING & SALES LLC

Premises Address (Changes? Notify the FFLC at least 30 days before the move.)
**4201 SOUTH US HWY 441
LAKE CITY, FL 32025-**

Type of License
01-DEALER IN FIREARMS OTHER THAN DESTRUCTIVE DEVICES

Purchasing Certification Statement
The licensee named above shall use a copy of this license to assist a transferor of firearms to verify the identity and the licensed status of the licensee as provided by 27 CFR Part 478. The signature on each copy must be an original signature. A faxed, scanned or e-mailed copy of the license with a signature intended to be an original signature is acceptable. The signature must be that of the Federal Firearms Licensee (FFL) or a responsible person of the FFL. I certify that this is a true copy of a license issued to the licensee named above to engage in the business specified above under "Type of License."

Mailing Address (Changes? Notify the FFLC of any changes.)

**SCOTTS GUNSMITHING & SALES LLC
4201 SOUTH US HWY 441
LAKE CITY, FL 32025-**

Scott A. Grews
Licensee Responsible Person Signature

Pres
Position Title

Scott A. Grews
Printed Name

3-12-11
Date

ATF Form 8 (5-3-10-11)
Revised September 20

Remington 700 B6216019

Discharges When Safety Released Recall?

386-752-9898

28.48

27. -

20. -

67.48

77. -

30.48

B6216019

Model: 700



RE00227320

*could not duplicate concern.
can offer to replace TPA, clean
+ test fire under BLP con.
\$20.00 + ship*

RECEIVED *Quote*
APR 07 2011

BY:





