

Remington Arms Co., Inc.
Product Service
Legal Case #:5846

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Prx Lit	Lit	Obsolete
222509	2/8/2011	2/9/2011	2/9/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Southland Gun Works	---	Southland Gun W	1228 Harry Byrd Hwy	Darlington	SC	29532		W 843-393-6291

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1028	Fired With Safe ON	Unknown	
C	FSO			

Dealer sent gun in for customer. Customer stated gun fired with safety on - wants bolt lock mod. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	290290	OP	7/1/1967
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE SCOPE BASE	U			

CONCERN:FSO

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM program	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	2/25/2011				

2/25/11: Per Ilion - Could not duplicate concern. TA is contaminated w/a dried & sticky lube residue causing parts to work sluggish. Replace TA, clean & test fire under BLM program - quote. Dealer apprvd quote & paid. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		2/9/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 22-250 REM
	Date Code		OP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Strip	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY, STICKY, PARTS WORK SLUGGISH
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

SOUTHLAND GUN WORKS, INC.



Across From The Raceway
1228 Harry Byrd Hwy.
DARLINGTON, SC 29532
www.southlandgunworks.com
(843) 393-6291

5846

24"
0P7/67
6
1008

CUSTOMER ORDER NO.		PHONE		DATE	
NAME		R.A. Co. Inc. (Attn: Service Dept)		Feb 2 2011	
ADDRESS		14 Hoefler Ave Elion, NY 13357		☐ SPECIAL ORDER ☐ GIFT CERTIFICATE ☐ LAY-AWAY ☐ TRADE-IN	
SOLD BY	CASH	CHARGE	C.O.D.	CHECK	ON ACCT.
QTY.	STOCK NO.	DESCRIPTION / SIZE		PRICE	AMOUNT
1		Remington 700 ADL 22/250 S&W #290290 with 2 weaver bases			
		* Warranty			
		- Customer states rifle fired			
		with safety on			
		- Bolt lock modification			
SPECIAL INSTRUCTIONS:				SUB-TOTAL	
- owner Larry Youngs PH # 864 246-3805				TAX	
				TOTAL	
				DEPOSIT	
REC'D BY				BAL. DUE	
Thank You					

B PRODUCT 2822

All claims and returned goods
MUST be accompanied by this bill.

**SPORTING
GOODS**

16434


RECEIVED
FEB 13 2011

BY: _____

Serial Number

290290

Model: 700



RE00222509

could not duplicate concern.
T.A. is contaminated w/a dried
sticky lube residue, causing parts
to work sluggish. replace TPA,
clean & test fire under BLP for
\$20.00 + ship

Quote

