

Remington Arms Co., Inc.
Product Service
Legal Case #:5947

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
222646	2/9/2011	3/1/2011	3/1/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Sportsman's Haven	---	Sportsman's Hav	14695 East Pike Rd.	Cambridge	OH	43725		W 740-432-7243

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

RARC sent gun in for customer. RARC stated safety issue. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/280 REM	25857	D6268914	KS	4/8/1998
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRYS SPORT CENTER INC	SCOPE BASE,BOTTOM HALF RINGS	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Hlon - Quote to repair	Repair/Replacement Cost	Repair/Replacement Date				

3/9/11: Per Hlon - TA rusty & causing parts to bind & work sluggish. Replace TA, clean & test fire @ 1/2 normal cost - quote. RARC apprvd quote & paid. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/1/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4015	Improper Maintenance	
Barrel	Description		22" 280 REM
	Date Code		KS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY, HAS RUSTED COMPONENTS
	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Not	RUSTED,PARTS BIND,WORK SLUGGISH

PURCHASE ORDER

11664

22"

PO # 5016

Date 02-04-11

To Remo

Address

City Elletts State OH Zip

4/9
125
7#
1012

FOR	DATE REQUIRED	HOW SHIP	TERMS
QUANTITY	PLEASE SUPPLY ITEMS LISTED BELOW		PRICE
	Remo		
	Md 700		
	Cal 280		
	SN# D6268914		
	Read Customers		
	Letter		
	Safety issue		
	Thanks		

SHIP TO:

SPORTSMAN'S HAVEN INC.
14695 EAST PIKE RD.
CAMBRIDGE, OHIO 43725
740-432-7243

Please Send Copies of Your Invoices

Purchasing Agent


RECEIVED
MAR 2 2011

BY: _____

Vertical text on the left margin.

D6268914

Model: 700



RE00222646

T.A. Rusty causing parts to
bind & work sluggish.
replace TAA, clean & test fire
at 1/2 normal cost.

Quote



