

Remington Arms Co., Inc.
Product Service
Legal Case #:5565

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
217159	1/3/2011	1/6/2011	1/6/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	T&T Gunnery		T&T Gunnery	3778 Merrick Rd	Seaford	NY	11783		W 516-221-7380

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

1/18/11 Per Ilion, could not duplicate concern. Trigger assm very dirty and set screws altered. Replace TPA, clean and test fire at 1/2 normal cost.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	27474	E6355055	LR	2/17/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART WAREHOUSE #3R	TWO PIECE BASE,RINGS,SCOPE	U			

CONCERN:PSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

1/18/11 Per Ilion, could not duplicate concern. Trigger assm very dirty and set screws altered. Replace TPA, clean, test fire at 1/2 normal cost. Dealer approved by phone on 1/14.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/6/2011
	Product Type		RP
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 243 WIN
	Date Code		LR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	ACT DIRTY FOREIGN DEBRIS
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,RINGS,SCOPE

5565

22"
LR2/97
2.5H

T&T GUNNERY

ATT: TONY

3778 MERRICK ROAD
SEAFORD, NY 11783

516-221-7380 FAX 516-221-7948

TO:

Remington

THE FOLLOWING HANDGUN / LONG GUN

MAKE:

Remington

MODEL:

700

SERIAL #:

E6355055

CALIBER:

BARREL:

ACCESSORIES:

Simmons 3x9 Scope

DESCRIPTION OF REPAIR:

Trigger Fixing when Turning
Safety Off

RECEIVED
JAN 17 2011


Serial
Number

E6355055

Model: 700

BY:

SINCERELY



RE00217159

REPAIR#: 6950

could not duplicate concern
T.A. VARY dirty + set screws
altered. Replace TPA, clean.
Test fire at 1/2 normal cost.

Quote