

Remington Arms Co., Inc.
Product Service
Legal Case #:6056

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
225929	3/28/2011	3/29/2011	3/29/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Willinghams Sports Inc.	---	Willinghams Spo	1405 Hwy 80 West	Demopolis	AL	36732		W 334-289-4652

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4038	Could Not Duplicate Concern	Unknown	
C	Safety is bad, Gun fired with Safety On, Chamber is bad	Concern:1028 Fired With Safe ON		

Dealer sent gun in with a note. They stated the gun's safety is bad, it fired twice with the safety on, and the chamber is bad. Dealer wants gun repaired. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	27518	E6597372	RT	11/8/1999 1:33:41 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	AMERICAN ROD & GUN		U			

CONCERN:FSO

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						

Repair/Replacement Cost	Repair/Replacement Date

4/5/11: Per Ilion - Could not duplicate concern. TA / action dirty & rusty. Can offer to replace TA, clean & test fire @ 1/2 normal cost. Will check chamber & repair - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		3/29/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		20" 243 WIN

Barrel	Date Code		RT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	SOME LITE RUST
	Stock Condition	Worn; Functioning	DIRTY, SCRATCHES, MARKS
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Remington Arms

Remington Model 700

Serial Number: E6957372


- The Guns Safety is bad.
- It has fired Twice with the safety on.
- The chamber is bad. It will not chamber a shell and eject it when the bolt is pulled Back

Please Make all repairs that are needed.

Willingham's Sports

E6597372

Model: 700



RE00226929

could not duplicate concern
T. A. / act. dirty & rusty. can
offer to replace TPA, clean &
test fire at 1/2 normal cost.
check out chamber & rep air.
Quote

RECEIVED
MAR 31 2011

BY: _____

Willinghams Sports, Inc.
1405 Hwy. 80 West
Demopolis, AL 36732
334-289-4652







