

Remington Arms Co., Inc.
Product Service
Legal Case #:6057

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
226948	3/28/2011	3/29/2011	3/29/2011				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gun Works of Central NY	---	Gun Works of Ce	5378 State Rt 31	Verona	NY	13478		W 315-363-7041 F 315-280-0841 E cnygunworks@hotmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Unexplained discharge			

Repair Center sent gun in with a note. They stated to please repair and ship back. Customer stated gun goes off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	722/222 REM	n/a	355179	CA	4/1/1954
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN:BOLT LOCK GOES OFF ON CUST.

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/722/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV

Per Ilion - Quote to repair under BLM

Repair/Replacement Cost	Repair/Replacement Date
\$27.64	4/5/2011

4/5/11: Per Ilion - Could not duplicate concern. TA set screws altered. Replace TA, clean & test fire under BLM - quote. I called repair center & spoke to Deborah Donovan. She apprvd quote & said to charge to open acct #. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/29/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 222 REM
	Date Code		CA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		M/722 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Uft	---Select---	.012
	Notch	Slightly Worn; Functioning	O/S DOUBLE
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	

6057

26"
CA 4/54
3.5"
.012

THE GUN WORKS OF CENTRAL NEW YORK

5378 STATE ROUTE 31

VERONA NEW YORK 13478

CNYGUNWORKS@HOTMAIL.COM


PH: 315-363-7041

FX: 315-280-0841

MARCH 18 - 2011

**PLEASE REPAIR AND SHIP BACK TO ABOVE
ADDRESS. THANK YOU.**

**BOLT LOCK-GUN GOES OFF ON
CUSTOMER.**




BY:

Serial Number: **355179**

Model: **722**

THANK YOU

REPAIR 78445



RE00226948

SERIAL NO. 355179

*could not duplicate concern.
T.A. set screws altered.
replace TPA, clean + test fire
under BCP for \$20.00 + ship*

Quote



