

Remington Arms Co., Inc.

Product Service

Legal Case #:5749

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
220454	1/24/2011	1/25/2011	1/25/2011				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Chris	Jashinski	701 Donna Ct	Clarksville	TN	37042		H 931-933-4479

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fires when safety is released	Cause:4006 Altered Adjustments or Components Concern:1007 Fired on Safe Release	Unknown	
C				

2/14/11 Per letter with rifle, Chris bought it at a yard sale and the rear sight was broken. He would like the front sight removed and for us to look at the bolt, spring and firing pin. It also fires when you take it off safe.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	722/300 SAVAGE	n/a	281336	XYX	12/1/1952
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE SCOPE BASE	N			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/722/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire under BLP for \$20 + shipping						
	Repair/Replacement Cost	Repair/Replacement Date				
	42.64	2/14/2011				

2/14/11 Per Ilion, trigger assem non-functional from set screws being altered. Replace TPA, clean, test fire under BLSM program for \$20 + shipping. Owner approved by letter on 2/7.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/25/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 300 SAVAGE
	Date Code		XYX
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/722 BOLT LOCK SAFETY
	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	O/S DOUBLE
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	NON FUNCTIONAL FROM SET SCREWS ADJUSTED TO FAR
	Pull	---Select---	10+#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		TWO PIECE SCOPE BASE


CHRIS JASHTENSKI
9311 933-4478
701 DOWNA CT
CLARKSVILLE TN 37042

11 LBS 1 OF 1
SHIP WT 11 LBS
DATE: 17 JAN 2011

SHIP BL SAFETY PROGRAM
TO: REMINGTON ARMS COMPANY INC
ILION FIREARMS PLANT
14 HOEFER AVE

ILION NY 13357-1888

NY 135 0-01



281336

Model: 722



RE00220454

5749

24"

4412/52

10T

1009

17.64

27. -

35. -

79.64

T.A. NON functional from set

37. -

SCREWS being altered.

42.64

Replace TPA, CLEAN + TEST RING

Under BLP for \$20.00 + ship

Quote

RECEIVED
JAN 27 2011

BY:

Dear Sirs
Of Remington Arms Co.
my model 722
sometimes fires when you
take it off safe.

if you would look at it
and let me know the cost
of the repair.

Thank you very much
Chris Jackson

Email address charmd415@aol.com

I bought the gun at a yard
sale. I put a scope on it
the rear site was broke
if you would replace front
and the broke part of the rear
site also if you would
have a look at the bolt, spring
and firing pin.

Thank

