

Remington Arms Co., Inc.
Product Service
Legal Case #:5662

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
219075	1/14/2011	1/17/2011	1/17/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Sportsmans Warehouse	---	Sportsmans Ware	6640 Lonetree Blvd.	Rocklin	CA	95765		W 916-782-9900 H 916-714-0355 W 916-716-0723
Incident		Jerry Lee	Angelich						

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

Dealer sent gun in for consumer. Their repair form stated the rifle fired spontaneously without bolt being fully closed, discharged while chambering a round using factory Hornady ammo. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM08 REM	85409	G6972126	PE	6/1/2010 8:31:07 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	PACIFIC FLYWAY WHOLESALE	SCOPE,RINGS,TWO PIECE BASE	U			

CONCERN:FBC

Ammunition Information

Mfg.	Type	Cal./Ga.	SKU	UPC	DOM	Mfg. Code
Hornady	/	7MM-08				
Concern	Other	Factory	Reload			
0:		Y	N			

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV

Per Ilion - Check over
& clean @ n/c

Repair/Replacement Cost	Repair/Replacement Date
\$27	2/4/2011

2/4/11: Per Ilion - Could not duplicate concern. TA functions as designed. Check over completely, clean & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/17/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		20" 7MM08 REM
	Date Code		PE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
Extractor	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Like new; Functioning	
Safety	Bulged	False	
	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	N/A
	Notch	Like new; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	



Repair Facility: Remington
 Address: 14 Hoefler Ave
 City: Jillson State: NY Zip: 13357
 RA/RMA Number: NA
 Insured Value: \$\$ 400

78"
 REC/10
 51

Store Information: (Use Store Address Stamp Here)

Sportsman's Warehouse
 6840 Lonetree Blvd
 Rocklin, CA 95765

5662

Store Phone Number: 916 782-9900

Firearm Information:

Manufacturer / Importer: Remington

Common Model: 700 SPS Youth Caliber/Gauge: 7mm 08

Serial Number: G6972126 Type: Rifle

Log Number: 4926-0797 (i.e. Store number (XX) followed by book (26) and log # - XX26-XXXX)

Shipped with the following: ☐ Magazine(s) ☐ Scope ☐ Rings ☒ Bolt
☐ Chokes ☐ Other Box

Problem: (Be as specific as possible)
Fired spontaneously without
Bolt being fully closed, discharged
while chambering a Remington-
Union Factory Ammo (Hornady
139551
740 R Grain)

Customer Name: Jerry Lee Angelich
 Customer Phone: 916 714-0355 / 916 716-0723

RECEIVED
 JAN 19 2011

BY: _____

rent by year.
 Rev. 4/08

G6972126
 Model: 700

 RE00219075

could not duplicate concern
 T.A. functions as designed.
 checked over completely, clean
 & rest firecracker MC
 warranty







