

Remington Arms Co., Inc.
Product Service
Legal Case #:5646

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
218777	1/13/2011	1/14/2011	1/14/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Dick Williams Gun Shop, Inc	Dick Williams G		4985 Cole Rd	Saginaw	MI	48601		W 989-777-1240

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

1/27/11 Per note from dealer, this gun discharged prematurely when the customer was taking the safety off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	27167	S6700063	DD	9/4/2009 6:31:34 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, check over completely, clean, test fire at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	27.00	1/27/2011				

1/27/11 Per Ilion, could not duplicate concern. Trigger assm is functioning as designed. Check over completely, clean, test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/14/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 3006 SPR XCR
	Date Code		DD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	

Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

C 511211

5646

24"
DD 9/09
3.54
.012

Dick Williams Gun Shop, Inc.

4985 Cole Rd.
Saginaw, MI 48601
989-777-1240

January 5, 2011

Remington Arms Co., Inc.
14 Hoefler Ave.
Ilion, NY 13357

Attn: Service Dept.

Sirs,

Enclosed please find one Remington 700, serial number S6700063, that is not working properly. This gun discharged prematurely when the customer was taking the safety off.

Please examine and repair or replace as needed. When complete, return to the address shown above. If you have any questions, do not hesitate to call.


Thank you for your assistance.

Sincerely,

Dick Williams Gun Shop, Inc.

S6700063


Model: 700



RE00218777

could not duplicate concern.
T. A. is functioning as designed.
check over completely, clean &
TEST fire AT N/C

WARRANTY



EY:.....

