

Remington Arms Co., Inc.
Product Service
Legal Case #:5683

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
219300	1/17/2011	1/18/2011	1/18/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Scheels	---	Scheels	2101 W. 41st St.	Sioux Falls	SD	57105		W 605-334-7767 F 605-334-8936

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C	FBC			

Dealer sent gun in for consumer. Dealer stated consumer claimed gun fired when bolt closed. Dealer was unable to duplicate problem. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	700/223 REM	84215	G6920966	RD	11/12/2009 1:49:39 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	MT SPORTS, LLC		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Check over completely @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$27	2/7/2011				

Per Ilion - Could not duplicate concern. TA functions as designed. Check over completely, clean & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/18/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE


Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 223 REM HB
	Date Code		RD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	011
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

5683

Scheels All Sports

Gunsmith Shop

2101 W 41st Street
Sioux Falls, SD 57105
Phone (605) 334-7767
Fax (605) 334-8936



January 7, 2011

Remington Arms Co
14 Hoefler Ave
Illion, NY 13357

Manufacturer: Remington
Model: 700
Serial Number: G6920966
Caliber or Gauge: 223
Service Order #: 22134

Enclosed is a Remington 700. The owner states that it will fire when the bolt is closed. We were unable to duplicate the problem. Please inspect and repair as needed under warranty.

Sincerely,

Eileen Fritz

Eileen Fritz
Gunsmith Office Manager


Enclosure

could not duplicate concern
T.A. functions as designed.
check over completely, clean +
test fire. N/C
warranty


Serial
Number:

G6920966

Model: 700



RE00219300



BY:



