

Remington Arms Co., Inc.
Product Service
Legal Case #:1

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
110469	4/3/2006	4/3/2006	4/3/2006				

Customer Information

Type	Business First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		West GA Sportsmans Warehouse	105 Sage Commercial Drive	LaGrange	GA	30240		W 706-845-1004
Incident	Scotty	Ray	1530 Armstrong Mill Road	Franklin	GA	30217		H 770-854-8643 C 404-788-6818

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PJ				
PD Truck door	Cause:4015 Improper Maintenance			
S Safety pushes hard and fire on safe release	Concern:1007 Fired on Safe Release		Unknown	
C				

The TA was rusted, the firing pin was rusted. The safety was hard to work due to the components being rusty.

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/220 Swift	29741	S6249820	RF	4/14/1994
Date Purchased	Where Purchased	Accessories	Original Owner			
	GANDER MOUNTAIN INC #110	camo tape on bbl and rec	U			

cust.concern: FSR shot door on friends truck and broke glass

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Clean action and install new TA n/c	N					
	Repair/Replacement Cost	Repair/Replacement Date				

Work to be done at n/c as gesture of goodwill. Charge 230145. Letter sent to customer. Repair and Shipping Document 4/19/06.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.Travis
	Exam Date		4/3/2006
	Product Type		RF
	Action Type		A
	Assigned To		F.Supry
Cause	4015	Improper Maintenance	rusty parts binding
Barrel	Description		24" 220 Swift SS
	Date Code		CO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Worn; Functioning	firing pin rusty
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	---Select---	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
	Notch Condition	Like new; Functioning	
Magazine	Condition	Slightly Worn; Functioning	
	Box Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	rusty inside, bolt squeaks when closed
	Bulged	False	
Safety	Description		standard M700 safety
	Function	Abused; Functioning	
Sear	Lift	---Select---	.014
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Worn; Functioning	trigger assm rusty and parts binding
	Pull	---Select---	3.5#
	Altered	False	