

Remington Arms Co., Inc.
Product Service
Legal Case #:4846

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		10/26/2010	10/26/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Tom	Snigier	14745 Inkster Rd	Livonia	MI	48154		E.snigier1@mi.rr.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
--------	-------	-------------	-------------------	----------------

PI

PD

5	Fired without pulling trigger	Cause:4079 Other - Unexamined Concern:1026 Jar-Off - No Mention of Safety Position	Unknown
---	-------------------------------	---	---------

C

10/26/10 Per email through Remington site, incident # 101020-000164, "MY 700 REMINGTON 30-06 HAS DISCHARGED WITH OUT PULLING THE TRIGGER----I JUST SEEN THE PROGRAM ON CNBC ---NOW I KNOW IT WAS NOT MY MISHANDLING OF THE FIRE ARM---PLEASE COME UP WITH A FIX I LOVE THE WAY THIS GUN SHOOT --THANK TOM SNIGIER --14745 INKSTER ROAD LIVONIA MICHIGAN 48154".cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06	n/a			
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
RARC is repairing						

Repair/Replacement Cost Repair/Replacement Date

10/26/10 Emailed that I would send prepaid shipping label for inspection at the factory.cm 10/26/10 Singier took it to Williams, RARC, for repair per his email through the RightNow Remington emails.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------