

Remington Arms Co., Inc.
Product Service
Legal Case #:6292

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
233746	6/15/2011	6/16/2011	6/16/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Palm Beach Shooting Center	---	Palm Beach Shoo	501 Industrial St.	Lake Worth	FL	33461		W 561-588-4867

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Dealer sent gun in. Dealer stated customer was shooting rifle at the bench & after several rounds had been fired - he moved the safety from safe to fire & the rifle fired. No damage, No injury. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM08 REM	27015	G6981384	PE	6/11/2010 5:00:33 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Replace TA @ n/c - warranty						

Repair/Replacement Cost	Repair/Replacement Date
\$52.88	6/24/2011

6/24/11: Per Ilion - Could not duplicate concern. TA functions properly. To restore confidence in rifle, will replace TA, clean & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/16/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM08 REM
	Date Code		PE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	EXCESSIVE LUBE ON BOLT ASSM
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE

6/13/11

6292

24"
PE 6/10
3.5#
.010

CUSTOMER WAS SHOOTING THIS RIFLE OFF OF THE
BENCH. AFTER SEVERAL WAS FIRED THE SAFETY WAS
TAKEN FROM THE ~~OFF~~ POSITION TO FIRE WITH A
ROUND IN CHAMBER AND THE ~~END~~ RIFLE FIRED.
THE RANGEMASTER WITNESSED THE EVENT AS
DESCRIBED. PLEASE GO OVER RIFLE AND RETURN.
Any: Question please call CHUCK AT 561 309 7211.
MGR Palm Beach Shooting Center.

ALM BEACH 
SHOOTING CENTER
.com
South Florida's Premier Indoor Range, Retail and Training Center

561.588.4867

Number: G6981384

Model: 700



RE00233746

could not duplicate concern.
T.A. functions properly. To restore
confidence in rifle will replace
TPA, clean + test fire at N/C
warranty

RECEIVED
JUN 22 2011

BY:.....









