

Remington Arms Co., Inc.
Product Service
Legal Case #:6095

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
228094	4/7/2011	4/8/2011	4/8/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Southland Gun Works, Inc		Southland Gun W	1228 Harry Byrd Hwy	Darlington	SC	29532		W 843-393-6291

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1023 Delayed Firing - Firearms			
C	Delayed firing			

4/19/11 Per note with rifle, customer says there's a delay in firing, that you can feel the trigger break and theres a delay before bolt plug moves forward.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	27017	G6881696	OD	7/15/2009 1:56:53 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SIMPSON PLAZA HARDWARE		U			

CONCERN: DELAYED FIRING

Ammunition Information

Mfg.	Type	Cal./Ga.	SKU	UPC	DOM	Mfg. Code
Remington	CL/165	30-06				
Concern	Other	Factory	Reload			
0:		Y	N			

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, will fit new TPA, clean, test at no charge as goodwill						
	Repair/Replacement Cost	Repair/Replacement Date				
	52.88	4/19/2011				

4/19/11 Per Ilion, could not duplicate concern. As a goodwill gesture and to restore confidence in rifle will fit a new TPA, clean, test fire under warranty.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/8/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 3006 SPRG
	Date Code		OD

Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	



SOUTHLAND GUN WORKS, INC.

Across From The Raceway

1228 Harry Byrd Hwy.

DARLINGTON, SC 29532

www.southlandgunworks.com

(843) 393-6291

6095

24"
007/09
4.5"
.011

CUSTOMER ORDER NO.		PHONE		DATE	
NAME		ADDRESS		DATE	
REMINGTON ARMS - SPRUCE DPT		14 HOFER AVE		MARCH 31 '11	
ADDRESS		ILION NY 13357		☐ SPECIAL ORDER ☐ *GIFT CERTIFICATE ☐ LAY-AWAY ☐ TRADE-IN	
SOLD BY	CASH	CHARGE	C.O.D.	CHECK	ON ACCT.
QTY.	STOCK NO.	DESCRIPTION / SIZE		PRICE	AMOUNT
		REMINGTON 700 CAL 30/06			
		SERIAL # G6881696			
WARRANTY					
CUSTOMER SAYS THERE'S A DELAY IN FIRING					
CUSTOMER SAYS YOU CAN FEEL THE TRIGGER BREAK AND THERE'S A DELAY BEFORE THE PLUG GOES FORWARD					
SPECIAL INSTRUCTIONS:				SUB-TOTAL	
SHOOTING 16GR CORE-CKT					
				TAX	
				TOTAL	
				DEPOSIT	
				BAL. DUE	
REC'D BY				Thank You	

27
25.88
52.88

RECEIVED
APR 15 2011

BY:

SPORTING
GOODS

All claims and returned goods
MUST be accompanied by this bill.

could not duplicate concern.
AS A Good - will gesture + to
restore confidence in rifle will
fit a new TPA, change test fire.

warranty

Serial Number

G6881696

Model: 700



RE00228094







