Remington Arms Co., Inc. **Product Service** Legal Case #:5689

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 227600 4/1/2011 1/18/2011 4/11/2011 11/11/2010

Customer Information

City State Zip Age Type Business First Name Last Name Street Contact Incident Tom Abbas 6652 Cooper Spur Rd. Mt. Hood Parkdale OR 97041 H 541-806-6273

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Shot a hole in truck door

Cause: 4038 Could Not Duplicate Concern

Unknown

S

Concern: 1007 Fired on Safe Release

C

Customer sent in a letter. He stated that on 11/11/10 he was hunting for bull elk. He returned to his his around 9:30am. He put his M/700 in the passenger seat of his truck & went into house & got truck keys. He drove the truck to a gate, had some coffee & listened to the news. He noticed that his rifle was still loaded & the bolt was closed. He placed the rifle onto the console w/right arm and then released the safety w/thumb & 1st finger. The gun fired, shooting a hole through the passenger door of truck. He stated it cost him \$2,395 to get door repaired. He feels he should be compensated for that amt & the rifle should be fixed. df

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga.

SKU n/a

Bbl. Serial DOM A6358425 DI 9/23/1976

Date Purchased

Where Purchased

700/7MM REM MA **Accessories**

Original Owner

CONCERN: FSR

BEND HDWE BEND OR SCOPE, RINGS, BASE, SCOPE COVERS

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Cash

Date Date APV APV

Repair under BLM @ n/c - goodwill gesture

> Repair/Replacement Cost

Repair/Replacement Date

\$30.40

4/11/2011

1/18/11: Sending ARS, letter, form. df 4/8/11: Per Ilion - Could not duplicate concern. Trigger pull 2.5 lbs., set screws altered & trigger not returning properly. I called customer & we agreed to repair at n/c under BLM - goodwill gesture. We will not cover truck repairs. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/4/2011
	Product Type		RF

	Action Type		la I
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM REM MAG
	Date Code		DI
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning]
1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select]
Receiver	Condition	Slightly Worn; Functioning	
receivei	Bulged	False]
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1000	False	
	Condition	Slightly Worn; Functioning	TRIG NOT RETURNING PROPERLY
 Trigger	Pull	Select	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE,SCOPE COVERS

Remington

X

24" 25%

5689

Tom Abbas 6652 Cooper Spur Rd. Mt. Hood Parkdale, OR 97041 Ph:

Ref: #5689

Dear Mr. Abbas,

A6358425

Model: 700

RE00227600

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

DECEIVED
APR 0 7 2011

BY:

enclosure

Sorry I did Not send THIS SOONER, WE WERE IN ARIZONA FOU THE WINTER TA.

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com TO: REMINGTON ARMS

Dec. 16, 2010

On Nov. 11, 2010 I decided to walk to the lower field in search of a bull elk. I returned to the house about 9:30 A.M. I place my Remington model 700 rifle in the passenger of my Dodge truck, barrel down, and went into the house to get my truck keys.

I drove my pick-up to the gate, overlooking the bottom field. I decided to have some coffee and listen to the news.

After a couple of minutes I noticed that my rifle still had a bullet in the chamber and the bolt was closed.

I am 61 years old and I never ever place a loaded gun in a vehicle..(except this once)

I placed the rifle onto the console with my right arm; I then released the safety with my thumb and first finger. At this moment the gun fired, shooting a hole through the passenger door of my truck. My hand was not near the trigger. I sat in shock for a minute, not believing what had just happened.

I now realized I had a bullet hole through my door and sore ribs from the kick of the gun. Thank God, no one was with me this day,

I recently got my truck out of the shop; it cost \$2395.00 to get the door repaired.

I believe I should be compensated for this amount, and my rifle should be fixed so it will never fire again, until the trigger is pulled.

I have not used it since the day it fired without pulling the trigger, and do not plan to until it is safe.

I can't sell it, knowing what I know about it, unless someone would like to buy it for testing purposes.

Thank You. I wait your reply.

Tom Abbas 6652 Cooper Spur Rd. Parkdale, Or. 97756

Print	Reset	
Model Number: 700	Serial Number: <i>A 6358425</i>	
Are you the original owner?: KYES NO		
Name: Tom Abbas	Date of Purchase: 1976 - 1980 Not Sure	
Address (no PO Boxes): 6652 cooper SPUR Ro		
City: PARKDALE	State: OR Zip: 97041	
Phone (Daytime): 541-806-6273 Fax: NONE		
E-mail Address:(if e-mail address is provid be sent)	ed, notification of receipt and shipment will	
E-mail Address: I would like to receive future e-mail updates from Remington.		
Please describe your problem and date of occurrence: Please see Letter!		
500 characters left		
Ammunition Information:		

Manufacturer: Reming toly mAG	Type: 7mm WW Super
Other (i.e. bullet	weight/type, shot size,
powder):	
Handloa	d Information:
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cle	aning and Lubrication):

Brand of cleaning solution used: outers	
How often do you clean the bore? (Months or Number of rounds) por year - 10 rounds	
How often do you clean the action? (Months or Number of rounds) / per year - 10 Rounds	
How often do you clean the trigger assembly? (Months or Number of rounds) 1 per year - 10 Rounds	
Brand of lubricant used: Outers Guy oil # 445A	
How often do you lubricate the bore? (Months or Number of rounds) / per year - 10 Round 3	
How often do you lubricate the action? (Months or Number of rounds)	
How often do you lubricate the trigger assembly? (Months or Number of rounds)	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > PYES NO Years AGO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) Never - Needs + Be !	
What were the services performed?)	
Ship your INSURED firearm by either UPS or Parcel Post to:	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper	

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		1/18/2011	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref# 5689 rifle			

LABEL INFORMATION

MAIL LABEL TO:	Tom Abbas 6652 Cooper Spur Rd. Parkdale, OR 97756
RETURN ITEM TO	Remington Arms
	Attn: Product Service
	Ilion, NY

REEASE COMPLETE ALL PARTISION THIS FORM AND SEND TO THE MEDIA COORDINATOR SERVICE

4XX596 JAN 18, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM
TRACKINGH 1Z4XX5969066710719
REF 1:TOM ABBAS/CD/DMF
REF 2:5689/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
DC 0.00 PR 0.00 SP 0.00
TOT PUB CHG 12.40 PUB+HANDLING 12.40









