

Remington Arms Co., Inc.
Product Service
Legal Case #:6184

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
231025	5/9/2011	5/10/2011	5/10/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bachelder	---	Bachelder	1229 Michigan Ave.	Grand Rapids	MI	49503		W 616-459-3636

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Dealer sent rifle in & stated that it fires when safety is removed. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	n/a	6588235	DW	9/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	MORLEY BROS SAGINAW MICH	SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	5/17/2011				

5/17/11: Per Ilion - Could not duplicate concern. TA dirty, sticky, rusty & set screws altered. Replace TA, clean & test fire under BLM - quote. Dealer apprvd quote & paid on open account #. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/10/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 2300 WIN MAG
	Date Code		DW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY,RUSTY
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE



1229 MICHIGAN N.E.
GRAND RAPIDS, MI 49503

24"
DW 9/7
2.5#
1007

DATE 5-5-11

6184

TO: Remington

CUST. Gemmen

Factory only

ATTN _____

OUR REPAIR NO. 38071

DATE RETURNED _____

ENCLOSURE

MAKE Ran MODEL 700 CAL. 300 GA. _____

SERIAL # 6588235 FINISH _____ GRADE _____

BARREL _____ ACCESSORIES _____

REPAIR ORDER

Fires when safety is removed

could not duplicate concern

T.A. dirty, sticky, rusty & set screws

altered. replace TPA, clean & test fire

under BCP for \$20.00 + ship

@ note

ESTIMATE REQUEST:

Please

☒ Only if not covered by warranty

☐ Only if charges are over \$ 17

☐ Not necessary

WE FEEL ITEM IS:

☐ Covered by warranty

☐ Not covered by warranty

☐ le to determine

ADDRESS ONLY!!!

RECEIVED

MAY 12 2011

BY _____

REGARDING THIS ITEM, PLEASE

116-459-3636, FAX: 616-459-7442

Number:

6588235

Model: **700**



RE00231025









