

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6132

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
226568	3/22/2011	4/21/2011	4/21/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	The Gun Shop	---	The Gun Shop	1023 15th Ave.	Longview	WA	98632		W 360-636-1230 F 360-636-3778 E thegunshop@comcast.net

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

Dealer sent rifle in. Dealer stated that his consumer had a FBC one time. Dealer made no mention of when this occurred. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	A6401623	BO	1/10/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	MUNSON SPTG COSTA MESA CA		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$62.90	5/6/2011				

5/6/11: Per Ilion - TA set screws altered - Trigger will not return properly. Replace TA, clean & test fire under BLM - quote. Dealer is mailing in a check to pay for repair. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/21/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 22-250 REM HB
	Date Code		BO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPRLY WILL FOLLOW DOWN
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

6132

24"  
30 1/7  
2#  
.009

Untitled

The Gun Shop  
1023 15th Ave.  
Longview, WA 98632

Ph: 360-636-1230  
FAX: 360-636-3778  
thegunshop@comcast.net

3-3-11

Remington Arms Co. Inc.  
14 Hoffer Ave.  
Illion, NY. 13357

Sirs,  
Please find enclosed 2 model 700 rifles for the bolt lock modification recall.

1. 700 BDL 270 Win. Sn / 17691
2. 700 BDL Varmint 22-250 Sn / A6401623

Our customer also says that the varmint model had discharged once while closing the bolt.

Please make any necessary repairs and contact us for credit card information when needed. Thank you!

Cordially

*John Bridges*  
John Bridges  
Owner

RECEIVED  
APR 27 2011

BY: \_\_\_\_\_

A6401623

Model: 700



RE00226568

T.A. Set screws altered, TR19  
will not return properly.  
Replace TPA, clean + test fire  
under BLP ROR \$ 20.00 + ship

Quote







