

Remington Arms Co., Inc.
Product Service
Legal Case #:6159

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
230073	4/29/2011	5/2/2011	5/2/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Jerry's Sport Shop		Jerry's Sport S	4075 Vickers St	Ambrose	GA	31512		W 912-359-3241 F 912-359-2274

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fires when you release safety Concern:1007 Fired on Safe Release			
C				

5/12/11 Per note with rifle, fires when you take it off safety.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	85560	G6547894	BA	10/18/2006 10:20:11 PM

Date Purchased	Where Purchased	Accessories	Original Owner
	NATIONAL WILD TURKEY FEDE	SCOPE BASE,MUZZLE BRAKE	U

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost.						

Repair/Replacement Cost	Repair/Replacement Date

5/12/11 Per Ilion, trigger assm set screws altered. Trigger not returning properly. Replace TPA, clean, test fire at 1/2 normal cost. Faxed estimate to Jerry's.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/2/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		26" 300 WIN MAG
	Date Code		BA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	SURFACE RUST ON METAL
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,MUZZLE BRAKE

2'0"
BA1/01
3#
10/12

6159

Fires of
When u
take it off
SAFTY

[Signature]



Jerry's
Sport Shop

Jerry M. Paulk, Owner
Michael Paulk, Manager
Lamar Fussell, Manager

4075 Vickers Street
P.O. Box 189
Ambrose, GA 31512
Bus: (912) 359-3241
Fax: (912) 359-2274
Tues.-Sat. 9am-6pm
Closed Sun. & Mon.

Number:

G6547894

Model: 700



RE00230073

RECEIVED
MAY 06 2011

BY:.....

T.A. set screws Altered. T117g. NOT
let unning properly. Repha TPA,
clean & Test fire AT 1/2 NORMAL
cost.

Quote

TRANSMISSION VERIFICATION REPORT

TIME : 06/06/2011 10:09
 NAME :
 FAX : 3365487823
 TEL :
 SER.# : BRO00J148005

DATE, TIME
 FAX NO. /NAME
 DURATION
 PAGE(S)
 RESULT
 MODE

06/06 10:09
 19123592274
 00:00:21
 01
 OK
 STANDARD
 ECM

Quotation

REMINGTON ARMS SERVICE

PO Box 700

Madison, NC 27025-0700

Estimating
Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00230073	Serial Number / Description G6547894 Model 700 Center Fire Caliber: 300 WIN MAG	Date Received: 04/29/2011 Estimate Date: 05/02/2011 Date Printed: 05/12/2011
Customer: JERRYS SPORT SHOP 4075 VICKERS STREET AMBROSE, GA 31512 US		Return To: JERRYS SPORT SHOP 4075 VICKERS STREET AMBROSE, GA 31512 US

Please Circle One:

VISA MC DISCOVER Card No. _____ Exp. Date _____
 Open Account: R _____ PO Number: _____

Approval Signature: _____ Date: _____
 Daytime Phone: (____) _____ Time to Call: _____

☐ If you desire any change, please use the reverse side for your comments and mark this box.

Reported M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION	Problems Found M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION
---	---

Technician Comments
 trigger assm set screws altered. trigger not returning properly. replace trigger plate assm, clean and test fire at 1/2 normal cost.

ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)

Material	Type	Description	Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLACK (OS)	1	Billable	1	94.00	50	47.00
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)	1	Billable	1	17.00	0	17.00
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50

Approved by phone *Golli*

Quotation

REMINGTON ARMS SERVICE

PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number	Serial Number / Description	Date Received:	04/29/2011
RE00230073	G6547894	Estimate Date:	05/02/2011
	Model 700 Center Fire Caliber: 300 WIN MAG	Date Printed:	05/12/2011

Customer:

JERRYS SPORT SHOP
4075 VICKERS STREET
AMBROSE, GA 31512 US

Return To:

JERRYS SPORT SHOP
4075 VICKERS STREET
AMBROSE, GA 31512 US

Please Circle One:

VISA MC DISCOVER Card No. _____ Exp.Date _____
Open Account: R _____ PO Number: _____

Approval Signature: _____ Date: _____

Daytime Phone: (_____) _____ Time to Call: _____

☐ If you desire any change, please use the reverse side for your comments and mark this box.

Problems

Reported

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Found

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Technician Comments

trigger assm set screws altered.trigger not returning properly.replace trigger plate assm, clean and test fire at 1/2 normal cost.

ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)

Material	Type	Description	Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLACK (OS)	1	Billable	1	94.00	50	47.00
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)	1	Billable	1	17.00	0	17.00
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50

Sub Total: 75.50
Est Sales Tax: 2.82

78.32

TRANSMISSION VERIFICATION REPORT

TIME : 05/12/2011 11:41
 NAME :
 FAX : 3365487823
 TEL :
 SER.# : BRO00J148005

DATE, TIME
 FAX NO. /NAME
 DURATION
 PAGE(S)
 RESULT
 MODE

05/12 11:40
 19123592274
 00:00:18
 01
 OK
 STANDARD
 ECM

Quotation

REMINGTON ARMS SERVICE

PO Box 700

Madison, NC 27025-0700

Estimating
Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number	Serial Number / Description	Date Received:	04/29/2011
RE00230073	G6547894	Estimate Date:	05/02/2011
	Model 700 Center Fire Caliber: 300 WTN MAG	Date Printed:	05/12/2011

Customer:

JERRYS SPORT SHOP
 4075 VICKERS STREET
 AMBROSE, GA 31512 US

Return To:

JERRYS SPORT SHOP
 4075 VICKERS STREET
 AMBROSE, GA 31512 US

Please Circle One:

VISA MC DISCOVER Card No. _____ Exp.Date _____
 Open Account: R _____ PO Number: _____

Approval Signature: _____ Date: _____

Daytime Phone: (____) _____ Time to Call: _____

☐ If you desire any change, please use the reverse side for your comments and mark this box.

Reported	Found
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Technician Comments

trigger assm sct screws altered.trigger not returning properly.replace trigger plate assm.clean and test fire at 1/2 normal cost.

ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)								
Material	Type	Description	Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLACK (OS)	1	Billable	1	94.00	50	47.00
4000114	Service	GR-SHIPING & HANDLING (GUN REPAIR)	1	Billable	1	17.00	0	17.00
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50







