

Remington Arms Co., Inc.
Product Service
Legal Case #:6156

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
229982	4/28/2011	4/29/2011	4/29/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Jesse D. Deyo Custom Gunsmith and Dealer		Jesse D. Deyo C	340 Windsor Hwy	New Windsor	NY	12553		W 845-565-2237 E jdeyo7@hvc.rr.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

5/11/11 Per note from dealer, his customer wants this rifle checked. Customer stated the rifle discharged accidentally when the safety was moved from safe to fire position without his finger on the trigger. This accident happened a while ago.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	20000	B6290045	DB	9/17/1981
Date Purchased	Where Purchased	Accessories	Original Owner			
	JOHNS SPORTING GDS CANTON OH		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

5/11/11 Per Ilion, could not duplicate concern. Trigger assm rusty. Can offer to replace TPA, clean, test fire at 1/2 normal cost. Approved by call to Nagle.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/29/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4041	Defective Ammunition Casing	
Barrel	Description		24" 22-250 REM HB
	Date Code		DB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	TRIG/ACTION RUSTY
	Pull	---Select---	4#
	Altered	False	TRIG WAS REPLACED 9/02 R# 51320
	Sub-Assembly	M/700 Non-Bolt Lock	

6156

JESSE D. DEYO
Custom Gunsmith and Dealer

24"
DB 9/81
4#
1012

340 Windsor Highway
New Windsor, NY 12553
(845) 565-2237
e-mail: jdeyo7@hvc.rr.com

April 20, 2011

Remington Arms Company, Inc.
Attn.: Arms Service Division/Repairs
14 Hoefler Avenue
Ilion, NY 13357

Dear Sir/Madam:

Enclosed is a customer's Remington, Model 700 Varmint Rifle, 22-250 Rem.,
Serial Number B6290045. Customer wants factory to check this rifle.

Customer states this rifle discharged accidentally when the safety was moved,
from "SAFE" to "FIRE" position. He also stated that he did not have his finger on
the trigger. This accident happened awhile ago.

Please check the rifle and repair if necessary.

A copy of my FFL should be on file with you.

If there are any questions, please feel free to call me or send an e-mail.

Thank you.

Sincerely,

Jesse D. Deyo
JESSE D. DEYO

RECEIVED
MAY 06 2011

BY:

Encl.
Remington Model 700 rifle, 22-250 Rem.

B6290045

Model: **700**



RE00229982

*could not duplicate concern.
T.A. Rusty. CAN offer to replace
TPA, clean & test fire at 1/2
normal cost.*

Quote









