Remington Arms Co., Inc. Product Service Legal Case #:6119

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

230767 5/6/2011 4/14/2011 5/9/2011

Customer Information

Business First Name Last Name Street City Contact Type State Zip Age H 772-465-2187 Incident Harold Keeney 230 Pulitzer Rd. Fort Pierce FL 34945 C 772-342-8292

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

S

PD Cause: 4038 Could Not Duplicate Concern

Concern: 1008 Fired on Bolt Closing

Unknown

C FBC

4/14/11: Cusotmer called in. He stated that he had FBC last year. No damage, No injury. His friend told him that he had the same incident with his so the customer is very concerned. df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/3006 SPRG 27123 G6552248 LA 2/1/2006 1:07:17 PM

Date Purchased Where Purchased Accessories Original Owner

WAL-MART DC 6003R-REGULAR Y

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date

APV APV

Per Ilion - Replace TA @ n/c to restore confidence in rifle

Repair/Replacement Repair/Replacement Cost Date

\$47.40 5/12/2011

4/14/11: Mailing ARS, letter, form. Box order# 1211338. df 5/12/11: Per Ilion - Could not duplicate concern. To restore confidence in rifle will replace TA, clean & test fire @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/9/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 3006 SPRG
	Date Code		LA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6119&Type=Case

5/12/2011

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	METAL RUSTY
Overall	Stock Condition	Slightly Worn; Functioning	MARS,SCRATCHES
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Print

Reset

Model Number: 700	Serial Number: (-6552248					
Are you the original owner?: YES NO						
Name: Harold Keeney	Date of Purchase:					
230 PUHZER RD Address (no PO Boxes):						
City: F+ PIERCC	State: 7-14 Zip: 3 49 45					
Cell 722 - Phone 342-8292 (Daytime): 772 - 465-2187	Fax:					
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)						
E-mail A						
	e-mail updates from Remington.					
Please describe your problem and date of occurrence: FIRES WHEN CLOSEING BOLT						
But Not every time						
have Not Shot more then 40 Roands						
	racters left					
Vianna, and the control of the contr						
Manufacturer: Type: 150 G-tain 30.06						
Other (i.e. bullet wei						
powder):	Annual Francisco Contract Cont					
Handload Information:						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used: \(\square\mathcal{O}\)					
Firearms Care (Cleaning and Lubrication):						
ВҮ:						

http://www.remington.com/asp/factory_repair_form.asp

Brand of cleaning solution used:	
How often do you clean the bore? (Months or Number of rounds)	
How often do you clean the action? (Months or Number of rounds)	
How often do you clean the trigger assembly? (Months or Number of rounds)	
Brand of lubricant used:	
How often do you lubricate the bore? (Months or Number of rounds)	
How often do you lubricate the action? (Months or Number of rounds)	
How often do you lubricate the trigger assembly? (Months or Number of rounds)	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >☑ YES ☐ NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)	
What were the services performed?)	•
Ship your INSURED firearm by either UPS or Parcel Post to: could not dup I wate a To MSTOM confidence in Mill replace them I Remington Arms Co., Inc. will replace TPA, clean in Attn: Arms Service Division for at N/c 14 Hoefler Avenue Ilion, NY 13357	oncepu in pifte in the

G6552248

Model: 700

RE00230767

SPENT SHELLS IN YOUR FIREARM OR IN HIS IS A VIOLATION OF FEDERAL LAW. IF IT SHELLS PLEASE SEND THEM IN A DE NAME, ADDRESS (WITH ZIP CODE), ERIAL NUMBER OF YOUR FIREARM.

of your firearm before sending it.

vent further damage in shipping and handling.
ferably,

Original boxes may not be returned.)

:: Remove an accessories non, your firearm to prevent loss or damage.
:: Provide a return address on both the outside and inside the box. Shipments without a proper



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		4/14/2011	REQUESTED BY:	Dell	
QUANTITY:	1		WEIGHT PER PKG:		10 lbs
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	xxxxxx	
DESCRIPTION:	Ref# 6119 rifle				

LABEL INFORMATION

MAIL LABEL TO: Harold Keeney
230 Pulitzer Rd.
Fort Pierce, FL 34945
Ph: 772-465-2187

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

APR 15, 2011 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 4XX596 SVC GNDCOM TRACKING# 124XX5969067004972 REF 1:HAROLD KEENEY/CD/DMF REF 2:6119/RIFLE HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: COD 0.00 DGD 0.00 RS 0.50 DV 0.00 DC 0.00 AH 0.00 SD 0.00 0.00 SP 0.00 0.00 PR 10.18 PUB+HANDLING TOT PUB CHG 10.18







