

Remington Arms Co., Inc.
Product Service
Legal Case #:6277

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
233328	6/8/2011	6/10/2011	6/10/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Lincoln Contractors Inc.	---	Lincoln Contrac	23934 Mervell Dean Rd.	Hollywood	MD	20636		H n/a
Incident		Mike	Abell						H 240-298-6227 C 301-373-3080

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Customer sent gun in with a note - stated that rifle fires when safety is released. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	700/17 REM	n/a	6446690 DU	9/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner		
	THOMAS DAVENPORT LEONARD TN MDREPAIR	TWO PIECE BASE	U		

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date	Cash Date
					APV	APV

Per Ilion - Quote to repair
under BLM

Repair/Replacement Cost	Repair/Replacement Date
\$30.40	6/24/2011

6/24/11: Per Ilion - TA very dirty & sticky. Set screws altered. Replace TA, clean & test fire under BLM - quote. Customer apprvd quote & paid by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/10/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 17 REM
	Date Code		DU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	FINISH REMOVED FROM BBL
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY
	Pull	---Select---	1#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

6277

24"
Du9/71
1#
1011

THE RIFLE FIRES WHEN
YOU GO FROM THE SAFETY
BEING ON SAFE TO
BEING ON FIRE WITHOUT
TOUCHING THE TRIGGER.
AND YOU HAVE TO HAVE
THE BOLT PULLED BACK
TO PUT IT ON SAFE.
TAKE A LOOK, SEE WHAT
YOU CAN DO, CALL ME
AT 240-298-6227
OR 301-373-3080 TO
LET ME KNOW. THANKS
MIKE ABELL

Serial
Number:

6446690

Model: 700



RE00233328

LINCOLN CONTRACTORS INC.
23934 Mervell Dean Rd.
Hollywood MD. 20636

T.A. very dirty & sticky. Set screws
altered. Replace TPA, clean & test
Rifle under B&P for \$20.00 + \$2.00

Quote

RECEIVED
JUN 22 2011

BY:







