

Remington Arms Co., Inc.
Product Service
Legal Case #:6200

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
231372	5/12/2011	5/13/2011	5/13/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Luthi's Inc	J.	Luthi	23 Butler Ave	Greenville	SC	29601		W 864-233-0551

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fires when closing bolt	Concern:1008 Fired on Bolt Closing		
C				

5/25/11 Per note with rifle, when bolt is engaged gun fires without pulling the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	27476	E6309724	DQ	9/9/1996
Date Purchased	Where Purchased	Accessories	Original Owner			
	GRADYS WHOLESALE SPORTS INC	SCOPE,RINGS,BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date

5/25/11 Per Ilion, trigger assm has a partially dried and sticky lube residue, parts work sluggish. Replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/13/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		DQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn;	

	Condition	Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	STICKY LUBE RESIDUE,PARTS WORK SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE

May 6, 2011

Remington Arms
14 Hoefler Ave
Ilion NY 13357-1816

RE: Remington 700
SN- E6309724

When the bolt is engaged gun fires with out pulling the trigger. Please repair or replace.
Thank you for your help in this matter.

Sincerely

J. Luthi
Luthi's Inc
23 Butler Ave
Greenville SC 29601
864-233-0551

E6309724

Model: 700



RE00231372

RECEIVED
MAY 20 2011

BY:.....

T.A. has a partially dried & sticky
Lube residue, parts work sluggish.
Replace TPA, clean & test Rifle AT
1/2 normal cost.

Quote

22"
DQ. 9/96
4#

6200







