

Remington Arms Co., Inc.
Product Service
Legal Case #:6248

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
232797	6/2/2011	6/3/2011	6/3/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Frankie	Perezchica	2216 Mission Blvd	Santa Rosa	CA	95409		H 707-540-0084

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance	Unknown	
S	Fires when working the bolt	Concern:1008 Fired on Bolt Closing		
C				

6/10/11 Per note with rifle, sometimes when working the bolt the gun fires by itself. It doesn't do it every time.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	n/a	A6598259	CQ	4/1/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	ADOLPH BLAICH RENO NE	SCOPE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	6/10/2011				

6/10/11 Per Ilion, trigger assm dirty and sticky. Set screws altered. Replace TPA, clean, test fire at BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/3/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		24" 308 WIN HB
	Date Code		CQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY WILL FOLLOW DOWN
	Pull	---Select---	1.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

May 23, 2011

24"
CQ 4/78
1.5
1009

6248

Remington Arms Co.

14 Hoesler Avenue

Ilion, New York 13357

Re: Model 700 Remington Serial #A6598259

Attention: Alfredo

I am returning the above gun in for repair, as sometimes when working the bolt, the gun fires by itself. It does not do it every single time, but, any time is not safe.

The rifle has always done this since I purchased it, so I just put it in my gun safe and have not fired it in years because I am afraid to use it. As you can see, this gun is like new.

Thank you.

Frankie Perezchica

2216 Mission Blvd.

Santa Rosa, CA. 95409

707-540-0084

Frankie Perezchica

Serial
Number:

A6598259

Model: **700**



RE00232797

RECEIVED
JUN 09 2011

BY: _____

*T.A. very dirty & sticky. set screws
altered. replace TPA, clean &
test fire under BLP Ron & 20.00 +
ship*

Quote







