Remington Arms Co., Inc. Product Service Legal Case #:6287

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

6/15/2011 6/15/2011 233647 6/14/2011

Customer Information

First Name Last Name Street City State Zip Age **Business** Contact Type

W 831-678-5519 PO Box 1020 Soledad CA 93960 F 831-678-5695

Reporter Salinas Valley State Prison Sgt. Morales Salinas Valley 31625 Hwy 101 E manuel.morales@cdcr.ca.gov

Incident Information

Medical Status Claims Codes Repair Est. **Medical Treatment**

PΙ PD

Cause: 4006 Altered Adjustments or Components

Unknown

Concern:1007 Fired on Safe Release S

C FSR

Agency sent rifle in. Stated that they experienced a FSR. No damage, No injury. df

Firearm Information

SKU Serial Bbl. DOM Mfg. Type Model/Ga. 700/308 WIN G6937430 DE3 1/1/1900 CF/BA n/a Remington

Original Owner Where Purchased Accessories **Date Purchased**

SALINAS VALLEY STATE PRISON SCOPE BASE, AFT MKT STK Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Date Cash Date Cash Release Date Reimbursement Settlement Release of Claims Settlement APV APV

Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

6/24/11: Per Ilion - Trigger has no return. Trigger pull set low. Will follow down. To restore confidence in rifle, can offer to replace TA w/XMP adj. TA, clean & test fire @ 1/2 normal cost - Quote. I faxed the quote to the Agency Armory for review, apprv. & payment. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/15/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	PULL SET BELOW MIN STANDARDS
	Description		20" 308 WIN POL FL
	Date Code		DE3
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6287&Type=Case

6/24/2011

	Condition	Slightly Worn; Functioning]
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	AFT MKT
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
Sear	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	HAS NO TRIGGER RETURN WILL FOLLOW DOWN
	Pull	Select	2#
	Altered	True	40X,PULL SCREW ADJ TO LOW
·	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,AFT MKT STK

Quotation

REMINGTON ARMS SERVICE

PO Box 700

Estimating Report

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00233647	G69	ial Number / Description 937430 del 700 Center Fire Caliber: 30	08 WIN				Date Re Estimat Date Pr	e Date:	06/14/2 06/24/2 06/24/2	011
Customer: SALINAS VALLEY STATE PRISON 31625 HWY 101 SOLEDAD, CA 93960 US				Return To: SALINAS VALLEY STATE PRISON 31625 HWY 101 SOLEDAD, CA 93960 US						
Please Circle One: VISA MC Open Account		Card No PO No	ımber:			Exp	o.Date			
Approval Signatur Daytime Phone	e:	alease use the reverse side for w	Time to	Call:	this ho	NV.	Date:			
If you desire any change, please use the reverse side for your comments and mark this box. Problems Reported M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION										
Technician Comments Trigger has no return with trigger pull set so low.Will follow down. To restore confidence in rifle can offer to replace with new x-mark pro adjustable trigger plate assm, clean and test fire at 1/2 normal cost										ndjustable
Material	Type	ΓΙΜΑΤΕ (note: C.O.D./Shipp Description	ing and Hand	C	irges ar Ity eded	e NOT Includ Warranty	led in this Q Qty From Inv	uote.) Price		Amount
	Part Service Service	700 XMP EA TRIG ASSB R GR-SHIPPING & HANDLIN GR-TEST		S) AIR)	1 1 1	Billable Billable Billable	1 1 1	115.00 17.00 23.00	0	57.50 17.00 11.50
								o Total: Sales Tax:		86.00 3.45
!							Gr	and Total		\$89.45

TRANSMISSION VERIFICATION REPORT

TIME

: 06/24/2011 10:36

NAME FAX

3365487823

TEL

SER.# : BROC0J148005

DATE, TIME FAX NO./NAME DURATION PAGE(S) RESULT MODE

06/24 10:35 18316785695 00:00:28 01 OK STANDARD

Quotation

4000119

Service

GR-TEST

REMINGTON ARMS SERVICE

ĒCM

PO Box 700

Madison, NC 27025-0700

Estimating Report

23.00 50

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

MIPRICES QUOTED BREIN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Numbe	r Se	rial Number / Description				Date Re	ceived:	06/14/2	011
RE00233647	G€	937430				Estimate	Date:	06/24/2	110:
	M	odel 700 Center Pire Caliber: 30	WIN			Date Pri	nted:	06/24/2	.011
Customer:				Retur	rn To:				
SALINAS '	VALLEY STAT	E PRISON		5	SALTNAS VAL	LEY STATE	PRISON		
31625 HW	Y 101			3	316 <mark>25 HWY 1</mark> 0	l			
SOLEDAD	, CA 93960 U	S		:	SOLEDAD, CA	. 93960 US			
		719				<u>,</u>			
Please Circle O		n				D-4			
VISA M	G DIZCOAE	R Card No PO Nu	*		Exp	.Date			
Open Accor	unt: R	PO Nur	nber:	-			·		·
A						Date			
Approval Signs	mure:	111111111111111111111111111111111111111	Ti to Co	71.		Date:			
		please use the reverse side for yo							
I It you des	ere suà cum de l'	picase use the reverse side for your	it comments and	THEIR INS O	OX.	en sentan nagan se es	The engine community	Train was parter of	With the control of the control of the
Reported		DOUCT SERVICE FOR INSPEC	Fo	ir nd					9 3 4 5 5 5 9 5 6
M123 - FOR	WARD TO PRO	DOUCT SERVICE FOR INSPEC	TION MI	23 - FORV	VARD TO PRO	DUCT SER	VICE FO	R INSPE	CTION
						_ 00 (00.0			J.14.1
		The Man Annual Control of the Contro							
	State Control of Association		Technician Col	mments	A Company of the			到阿里爾	
		ger pull set so low.Will follow do st fire at 1/2 normal cost	while restore co	ntidence in i	ritie can offer to	replace wit	h tiew x-n	iark pro	ødjustable
,			A DESCRIPTION OF THE PARTY						The second second second
Material	Type	TIMATE (note: C.O.D./Shippi Description	ng and Handlin	g Charges a Qty	re NOT Includ Warranty	ed in this Q Qty	uoted		Amount
17AUCOI IAI	хурс	s escription		Needed	, varianty	From Inv	FIICE	Disc	AMOUNT
F306371B	Part	700 XMP EA TRIG ASSB RI	BLACK (OS)	1	Billable		115.00	50	57.50
4000114	Service	GR-SHIPPING & MANDLING	(GIIN REPAIR	1 1	Billable	1	17 00	<u> </u>	

1

Billable

11.50

DIVISION OF ADULT INSTITUTIONSSALINAS VALLEY STATE PRISON

P.O. Box 1020 Soledad, CA 93960 1,287



017

March 24, 2011

Remington Arms Company, Inc.

14 Hoefler Ave.

Ilion, NY 13357

TEL: 1-800-243-9700 Fax: 1-315-895-3227

ATT: Tom Nagle

Enclosed please find one (1) Remington Model-700 308 serial # G6937430 . Upon inspection of this weapon the malfunction(s) listed below were discovered. These repairs are beyond the scope of our ability as Factory Certified Armorers to repair. Please facilitate this repair at the factory and advice of the cost associated (if any). This weapon is assigned to our CRT training department.

- Remington, Model-700 serial # G6937430
- When moving weapon from safe to fire position the weapon will discharged. (with out pulling the trigger)

Please note:

When returning this weapon, please inform shipper to deliver the package directly to the Institutional Armory not the warehouse, as there are minimum-security inmates working at that location. Please have the shipping representative contact me 24 hours prior to delivery, to coordinate the drop-off.

If you have any questions or require additional information please contact Armory Staff at (831) 678-5519.

M. Morales

Armory Sergeant

Salinas Valley State Prison

Manuel Morales@cdcr.ca.gov Armory Tel: (831)678-5519

Armory Fax: (831)678-5695

Trig. has NO return with Trig.

pull set low. Will follow down:

To restore confidence in rifle

can offer to replace w/ xmp Adj
TRA, clean + Test fine, At 1/2

NORWAL cost.

Quate

で Model: 700 Model: 700 RE00233647

BY:----







