

Remington Arms Co., Inc.
Product Service
Legal Case #:6238

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
232375	5/27/2011	5/31/2011	5/31/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Simmons Sporting Goods	---	Simmons Sportin	2001 Second Ave. N.	Bessemer	AL	35020		W 205-426-0490

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C	FBC			

Dealer sent gun in with a note. Dealer stated bolt handle was broken & last round that was chambered went off by itself. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300RUM	26010	S6382523	RU	11/4/2000 1:02:00 AM

Date Purchased	Where Purchased	Accessories	Original Owner
	SIMMONS SPORTING GOODS	SCOPE BASE,AFT MKT STK	U

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						

Repair/Replacement Cost	Repair/Replacement Date

6/10/11: Per Ilion - TA dirty & sticky. Set screws altered. Replace TA, clean & test fire @ 1/2 normal cost - quote. Quote was apprvd & paid for w/credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/31/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		26" 300 RUM SS FL
	Date Code		RU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn; Functioning	

	Condition		
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Abused; Not Functioning	SEPARATED FORM BODY
	Stop	Like new; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	BBL SCRATCHED
	Stock Condition	---Select---	AFT MKT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY.
	Pull	---Select---	2.5# CHECKED WITH SLAVE BOLT ASSM
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,AFT MKT STK

6238

26 11
R 6 11/20
1012
2.5#

DATE RETURNED (5-20-11)

RETURN #

FROM: SIMMONS SPORTING GOODS
2001 SECOND AVENUE N.
BESSEMER, AL 35020
(205)426-0490

SHIPPED BY

UPS (✓) LBS
TRUCK () LBS
OF CARTONS

RETURNED BY
OF ITEMS
FACTORY RA#

RETURN TO: Kenington

REASON FOR RETURN: bolt handle broken and lost
round nut was chambered went off
by itself. Thanks
Russell Bracke

ITEMS RETURNED: 700 SS Fluted 300 UM
Serial # S6382523
Repair # 3017

RECEIVED
JUN 09 2011

BY:

Serial Number:

S6382523

Model: 700



RE00232375

J.A. Dirty & sticky, set screws
altered. replace TPA, clean &
Test fine at 1/2 normal cost.
Q code







