

Remington Arms Co., Inc.
Product Service
Legal Case #:6094

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
228013	4/7/2011	4/8/2011	4/8/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Sportsman's Headquarters		Sportsman's Hea	1201 N. Eastern Blvd	Montgomery	AL	36117		W 334-396-5297

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired when safety was released	Concern:1007 Fired on Safe Release	Unknown	
C				

4/19/11 Per note with rifle, accidental discharge when safety was taken off to unload.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6793873	PV	7/5/1979
Date Purchased	Where Purchased	Accessories	Original Owner			
	SOUTHERN GUN DIST OPA LOCKA FL		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	40.62	4/19/2011				

4/19/11 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean and test fire under BLSM program price of \$20 + S&H.cm 6/2/11 Dan at Walter Craig approved. Wants it charged to their acct. I'm checking with Slagle. They are not set up for PR dist.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/8/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		PV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Walter Craig's

THE SPORTSMANS HEADQUARTERS

Customer Return Form

1201 N. Eastern Blvd. Montgomery, Alabama 36117

Phone: 334-396-5297 Fax: 334-396-5296

6094

22"
PU 4/79
4#
1008

Name:

HARRY McMillan

Phone:

Address:

Factory RA # (If Applicable)

Ref #

Please put this # on replacement merchandise

Should you have any questions concerning this return, please call JAMES HALLFORD at 334-396-5297

ITEM #	Catalog #	Mfg. #	Serial #	Description	Reason for Return
			A6793873	Remington 700 BDL LH 30-06	Accidental discharge when safety was taken OFF to unload.
					RECEIVED
				could not duplicate concern. T.A. dirty + set screws altered. Replace TPA, clean + test fire under BCP for \$20.00 + ship	APR 15 2011

BY:

Repair Charges	
Freight charges to the Factory	
Freight Charges from the Factory	
TOTAL AMOUNT DUE	

Quote

I agree to pay all freight charges to and from the factory as well as any repair charges from the factory in full. I understand that all returns are subject to the manufacturer's warranty, terms & conditions. ☐ Yes. I would like insurance. **I understand that insurance does not always cover damages that occur during shipment to the factory and will assume that responsibility.** (.50 cent extra per \$100 insured)

Customer's Signature: _____

Date: _____

ge item(s) to prevent damage during shipping to and from the factory, will not occur if merchandise is not in the original factory packaging. I assume ur. Customer's signature: _____

FOR OFFICE USE ONLY

Repaired/Replaced Product Received: _____

Method of Payment: _____

Serial Number:

A6793873

Model: 700



RE00228013

 30.62
 27. —
 28. —
 77.62
 37. —
 120. —







