

Remington Arms Co., Inc.
Product Service
Legal Case #:6075

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
227598	4/1/2011	4/4/2011	4/4/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Stocker's Shop	---	Stocker's Shop	5199 Mahoning Ave.	Warren	OH	44483		W 330-847-9579

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

Dealer sent gun in for consumer. Dealer stated the rifle fires when cocking. Does not fire everytime when bolt is being closed but occassionally fires. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6470785	WU	8/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	JOHNS SPRTG GD CANTON OH		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	4/11/2011				

4/11/11: Per Ilion - TA dirty & sticky causing parts to work sluggish. Replace TA, clean & test fire under BLM - quote. I called dealer & he apprvd & pd by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/4/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
	Description		22" 3006 SPRG
	Date Code		WU

Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY.PARTS WORK SLUGGISH
	Pull	---Select---	7#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

STOCKER'S SHOP

STOCKER'S SHOP
5199 Mahoning Ave

Warren OH, 44483

(330)-847-9579

6075

22#
WUG
7#
1008

NAME _____
ADDRESS _____
CITY _____
STATE _____
ZIP CODE _____
PHONE # _____

Number:

6470785

Model: 700



RE00227598

FIREARM DESCRIPTION

MAKE REMINGTON
MODEL 700
CAL. 30-06
BARREL 28
SERIAL # 6470785
LOG# R467

FFL WHO WILL BE SHIPPING/RECEIVING

Date 3-17-11

FFL DEALER REMINGTON
ADDRESS _____
CITY _____
STATE _____
ZIP CODE _____
PHONE # _____
FAX# _____
FFL# _____

T.A. DIRTY + STICKY CAUSING PARTS
TO WORK SLUGGISH. REPLACE TPA,
CLEAN + TEST FIRE UNDER BCP
FOR \$20.00 + SHIP

quote

INDIVIDUAL RECEIVING FIREARM

~~NAME~~ - PROBLEM -
~~ADDRESS~~ • FIRES WHEN COCKING
~~CITY~~ DOES NOT FIRE EVERYTIME WHEN BY: _____
~~STATE~~ BOLT IS BEING CLOSED, BUT
~~ZIP CODE~~ OCCASIONALLY FIRES
~~PHONE #~~ _____

RECEIVED
APR 07 2011







