Barrel

Remington Arms Co., Inc. Product Service Legal Case #:6124

Case Information Pre Lit Lit **Date Opened** Date Opened(PS) **Date Closed** Incident Date Obsolete RE# 230795 5/6/2011 4/18/2011 5/9/2011 Customer Information First Name Last Name Street City Zip Age Contact Business State Type H 218-681-3231 16343 160th NE W 218-681-2184 Thief River MN 56701 Incident Wigand Barbers Steven Wigand bus add: 1513 Hwy 59 Sout C 218-686-9108 Incident Information Repair Medical Medical Claims Codes Est. Treatment Status PΙ PD Cause:4038 Could Not Duplicate Concern Concern:1005 Unexplained Discharge Safe  $\frac{1}{1}$ Unknown Fired with safety on when leaning against S C 4/18/11 Per call from Wigand, his 700 has a serious safety issue. When he laid it against the wall of the deer stand, safety was on, it went Firearm Information Type Model/Ga. SKU DOM Mfg. Remington CF/BA 700/30-06 SPRG n/a B6271273 PS 12/23/1998 **Original Owner Date Purchased** Where Purchased Accessories SIMMONS GUN SPEC OLATHE KS TWO PIECE BASE Said he bought it about 10 yrs ago. CONCERN:FSO Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Reim. Date Cash Date Cash Reimbursement Settlement Release of Claims Release Date Settlement APV APV Per Ilion, replace TPA, clean, test fire at 1/2 normal cost Repair/Replacement Repair/Replacement Date 4/18/11 Sending box and ARS from Corporate.cm 5/13/11 Per Ilion, could not duplicate concern. Can offer to replace TPA, clean, test fire at 1/2 normal cost.cm 117 Emailed inspect into Examination[Remington/CF/BA] Part Sub-Part Code Comment Examiner B.TRAVIS 5/9/2011 Exam Date Examination Product Type RFAction Type Assigned To T.NAGLE 4038 Could Not Duplicate Concern Cause Description 22" 3006 SPRG DM Date Code

False

False

False

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6124&Type=Case

Bore Plugged

Bulged

Fired

5/13/2011

	Fired while Obstructed	<u></u>	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
		Slightly Worn; Functioning	<del></del>
Bolt	Firing Pin		<del> </del>
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
1	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
_	Sub-Assembly	Non-ISS	
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

22" PS6/98 4.5#

6124

April 18, 2011

Steven Wigand Wigand Barbers 1513 Hwy 59 South Thief River, MN 56701

Subject: #6124, Model 700


Dear Mr. Wigand,

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the boxes with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



D6271273

Model: 700

RE00230795

could not dup liente concern. CAN often to suplace TPA, clean trest Rine pt 1/2 Morand cost.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Model Number: 700 Rem 30-6	Serial Number: P-627/273
Are you the original owner?: YES NO	
Name: Steven W. WISGAND	Date of Purchase: Z000
Address (no PO Boxes): 1513 H	WY 59 50.
city: Thief River	State: MN. Zip: 5670/
Phone (Daytime): 218 681-2184	Fax: N/A
Sent) Wi GAND BAV Letter	of receipt and shipment will be  Comp. L. Com
E-mail Address:	nington UES
Please describe your problem and date of occurrence:	<u> </u>
Safetan probl	em.
when Safety	is on
500 characters left	
Ammunition Information:	
Manufacturer: Tederal	Type: 30-6.
Other (i.e. bullet weight/type, shot size, powder):	······································
150 Gr.	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Buliet Type/Shot Size:	Reloader Used:

Case #	6124	Date of Call	4/18/11	Date of Incident		PreLit Lit	Obs	60
Reporter name address				Incident Name/Age address / v	25/e	ven Wir 43 160th,	gand N.E. Thier MA SOUAL 56701	River 1 5670
contact #'s				contact #'s	1513 Thirt	this Sire River; MN 218-681-	504A 56701	
email				email	10 - 2	218 - 68   - 218 - 68   - 18 - 68 6 -	2184	
Injury Medical Treatment								
Alleged cause					10 y1	rs, ago		
Firearm 760	Ser# PG271273	Cal 30-06	DОМ 180	Orig owner?	When/W	/here purchased		
Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot #	Additional info		
Other Product								
	safety	issue,	laid invent	ne i	sall	a gainst	deer	
	37474							
Notes:								
Request	ł							



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE: 4/18/20	11 REQUESTED BY:	christy
QUANTITY:	1 WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE:		
MEDIA		
COORDINATOR		xxx
TO MAIL	I WILL MAIL	
DESCRIPTION:		
7	00	
B6271273		

### LABEL INFORMATION

MAIL LABEL TO:	Steven Wigand	
	Wigand Barbers	
	1513 Hwy 59 South	
	Thief River, MN 56701	
	218-681-2184	
RETURN ITEM TO	D D   D	 <del></del>
LE LOKIN HEIM IC	r: Rem Prod Serv	
RETORNTEWIC	r: Rem Prod Serv	
RETORNTIEMTC	r: Rem Prod Serv	
RETORNTEMIC	r: Rem Prod Serv	
RETURNITEMIC	r. Kem Prod Serv	

#### PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 APR 19, 2011 ALL CURR USD SVC GNDCOM ACT UT 10.0 LBS TRACKING# 1Z4XX5969066781474 REF 1: WIGAND BARBERS/STEVEN W/CD/CM REF 2:700./B6271273 4XX596 1 OF 1 HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 DC 0.00 COD 0.00 RS 0.50 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 10.18 PUB+HANDLING 10.18

## **QUOTATION**

Repair Order Number

# Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700 Madison, NC 27025-0700 ESTIMATING REPORT

5/7/2011

Date Received -

Parts/Repairs Fax 800-243-9700 336-548-7801

www.remington.com info@remington.com

#### ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Description/Serial Number

RE00230795 Account # - R-					te Date - it Date -	5/9/2011 5/9/2011
Customer STEVEN WIGAND 1513 HWY 59 SOUTH				'o N WIGAN VY 59 SO		
THIEF RIVER FALLS. MN 56701	US		THIEF R	RIVER FA	LLS. MN	56701 US
Phone (H) (218)-681-2184 Phone (W)	REDACTED -	Fax Email	WIGANI	<u>BARBER</u>	S@G.MAI	L.COM
Please Circle One (VISA) MC AMEX DISCOVER Card PO Number	No	5577	Exp.	Date_ RI	EDACT	ED
Daytime Phone (2/8) 681-2189 Approval: Customer Signature	Time To Call AN			en Acct. <u>R</u>		13-11
If You Desire Any Change Please U	Notice: We process checks elect			Γhis Box		
Reported	Problem	ns <u>Found</u> *				
M123 FORWARD TO PROF FOR INSPECTIO	DUCT SERVICE	M123	FOR	WARD TO	PRODUC	T SERVICE F
A THE CONTROL OF THE	Technician's Concern.can offer to replace	The Control of the Co	en er entstelle statistisk in ekonomie stelle stelle	Personal Annual Programme Company	norther water the control of the con	normal cost
Estimate **C.O.D	./Shipping and Handling (	Charges are	NOT Includ	led in this (	Quote	and the second s
Material # Material Description		<u>Oty</u>	Warranty Y/N	<u>Price/</u> <u>Unit</u>	Discount Percent	Extended Amt
Part   F305570B X-MARK PRO 700 TRI   Service	G ASSB RH BLACK (O	1	N	\$94.00	50%	\$47.00
4000114 GR-SHIPPING & HANI 4000119 GR-TEST	DLING (GUN REPAIR)	1 1	N N	\$17.00 \$23.00	0% 50%	\$17.00 \$11.50
Dagaba	MA'	Y 16 20	11	Sub Total		\$75.50
The Market of the Control of the Con	d Dato:	ليعدننين بالمحاطا	ها لبيت	Est. Sales 7 Grand To		\$3.06

1.00/01186/1...





