
Remington Arms Co., Inc.
Product Service
Legal Case #:6003

				egai Case #:6003							
Case Inform	nation										
RE # 228499	Date Opened 4/11/2011		e Opened(PS) 3/16/2011	Date Closed 4/19/2011	In	cident :	Date	Pre	Lit Li	t O	bsolete
	information		3/10/2011	1/17/2011			-	- •			
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age	C	ontact	:
Reporter	Woodsbay Gunsmithing	****	Woodsbay Gunsmi	13390 Montana Hwy 35	Big Fork	MT	59911		W 406 C 406		
	Ounsmaning		Guiisiiii	11117 33	POIN			d	majerus@		rytel.net
ncident In	formation										
	Claims		Code	es	Rep	air Est		Medio Treatm			edical atus
PI								1 I Catil	СПІ	3	atus
	mer shot a hole in	Cause	:4038 Could N Concern	ot Duplicate				Unkno	wn		
3		Conce	rn:1007 Fired on	Safe Release							
C FSR											
				his rifle in & stated sumer wants us to		d on saf	e rele	ase & sł	not a hole	in his	truck.
	not have a date of		or what the cons	ounier wallis us to							
irearm In	formation										
Mfg.		Type		Model/C				KU			DOM
Remingt	on	CF/BA	A	700/22-250	REM		n	/a	641967	8 CW	4/1/1972
_											
Date	ed W	here Pur	chased	Accessor	ries			ginal mer			
_	ea	GUN HDQ	TRS DAYTON	TWO PIECE B	ASE,ST	ΓK.	Ow	ginal mer			
Date	DAYTON (TRS DAYTON		ASE,ST	ГК.	Ow	ner			
Date Purchas	DAYTON (GUN HDQ OHIC	OTRS DAYTON	TWO PIECE B	ASE,ST	ГК.	Ow	ner			
Date Purchas	DAYTON (V:FSR on Information - N	GUN HDQ OHIC	OTRS DAYTON	TWO PIECE B	ASE,ST	ГК.	Ow	ner		A SERVICE STATE OF THE SERVICE	a may a separation of the sepa
Date Purchas CONCERN Ammunition Other Prod	DAYTON ON:FSR on Information - Nucts Information -	GUN HDQ OHIC	OTRS DAYTON	TWO PIECE B	ASE,ST	ГК.	Ow	ner		AMBRION, WHITE CONTROL	
Date Purchas	DAYTON ON:FSR on Information - Nucts Information -	GUN HDQ OHIC	OTRS DAYTON ed fined	TWO PIECE B.	ASE,S7	гк.	Ow	ner	<u> </u>		
Date Purchas CONCERN Ammunition Other Prod	DAYTON ON:FSR on Information - Nucts Information -	GUN HDQ OHIC	OTRS DAYTON ed fined	TWO PIECE B	ASE,S7	ГК.	Ow	mer J	R	eim.	Cash
Date Purchas CONCERN Ammunition Other Producttlement	DAYTON (N:FSR on Information - N ucts Information -	GUN HDQ OHIC one Defin None Def	ed fined Rem	TWO PIECE B.	ASE,S7		Ow	ner	ent E	ate—	Cash
Date Purchas CONCERN Ammunition Other Product of the Product of	DAYTON (N:FSR on Information - N ucts Information - ment——— Rele	GUN HDQ OHIC one Defin None Def	ed fined Rem	TWO PIECE B. BOOT	ASE,S7		Ow	rner J Cash	ent E		
Date Purchas CONCERN Ammunition Other Product of the Product of	DAYTON (N:FSR on Information - N ucts Information - nent Rele n/c under boodwill ure	GUN HDQ OHIC one Defin None Def	ed fined Rem	TWO PIECE B. BOOT	ASE,S7		Ow	rner J Cash	ent E	ate—	—Date-
Date Purchas CONCERN Ammunition Other Product of the Product of	DAYTON (N:FSR on Information - N ucts Information - nent Rele n/c under boodwill ure	GUN HDQ OHIC One Defin None Def ase of Cla r/Replace Cost	ed fined Rem ims — Re	TWO PIECE B. BOOT	ASE,S7		Ow	rner J Cash	ent E	ate—	—Date-
Date Purchas CONCERN Ammunitic Other Producttlement	DAYTON ON STATE OF THE PROPERTY OF THE PROPERT	GUN HDQ OHIC One Defin None Def ase of Cla r/Replace Cost \$30.40	ed fined Rem ims — Re ment Repair	TWO PIECE B. BOOT	ASE,ST	urseme	Ow	Cash Settlem	ent A	Pate PV	—Date- APV
Date Purchas CONCERN Ammunition Other Producttlement Settler Repair @ r BLM - g gestr /16/11: Set Left him ruck repair	DAYTON ON:FSR Information - No ucts Information - No ucts Information - No ucts Information - Release to the codwill ure Repaired to the code of the	one Define None None Define None None None None None None None No	ed fined Rem Aims — Re 4/15/11: Per Ilion willing to replace w/dealer - we wi	TWO PIECE B. BOOT mington/700/CF/BA lease Date — — f/Replacement Date /19/2011 n - Could not dupli e TA, clean & test ll replace TA, clea	ASE,ST	urseme	Own	Cash Settlem M @ n/	ent A	PV alled c	Date APV
Date Purchas CONCERN Ammunitic Other Producttlement Repair @ n BLM - gr gestn /16/11: Set left him ruck repair	DAYTON ON:FSR Information - No ucts Information - No ucts Information - No ucts Information - Release to the codwill ure Repaired to the code of the	r/Replace Cost \$30.40 form. I am agreement	ed fined Rem Aims — Re 4/15/11: Per Ilion willing to replace w/dealer - we wi	TWO PIECE B. BOOT bington/700/CF/BA lease Date — — c/Replacement Date /19/2011 1 - Could not duplie TA, clean & test	ASE,ST	urseme	Own	Cash Settlem M @ n/	ent A	PV alled c	—Date—APV

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6003&Type=Case

4/19/2011

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		4/12/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE -
Cause	4038	Could Not Duplicate Concern	
	Description		24" 22-250 REM
	Date Code		CW
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	FINISH WEAR
Overall	Stock Condition	Slightly Worn; Functioning	MARS,SCRATCHES
	Fore End Condition	Select	
Dagaiyar	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description]	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 0303	False	
	Condition	Slightly Worn; Functioning	SOME DIRT
Trigger	Pull	Select	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,STK. BOOT



Woodsbay Gunsmithing 13390 Montana Hwy 35 Big Fork, MT 59911 Ph: 406-837-1101

Ref: #6003, M/700, Serial #6419678

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

APR 1 5 2011 BY:

6419678 Model: 700 RF00228499

> Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Print

Reset

Model Number: 700	Serial Number: 64/9678						
Are you the original owner?: YES NO							
Name: Woodsbay Gunsmithing	Date of Purchase:						
Address (no PO Boxes):							
13390 MT. Hwy 35							
City:-Bigfork	State: MT Zip: 59911						
Phone (Daytime): 406 - 837-1/01	Cell 406-250-8038						
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) dmajerus century tel net							
E-mail Address:							
Please describe your problem and date of occurrence:							
customer shot is truck while taking							
Saftey off, with live round in chamber 500 characters left							
Ammunition Information:							
Manufacturer: Type:							
Other (i.e. bullet weight/type, shot size, powder):							
Handload Information:							
Powder Used: Powder Weight:							
Case/Hull Used:	Primer Used:						
Bullet Type/Shot Size:	Reloader Used:						
Firearms Care (Cleaning and Lubrication):							

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES □ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		3/16/2011	REQUESTED BY:	Dell	
QUANTITY:	1		WEIGHT PER PKG:		10 lbs
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	xxxxxx	
DESCRIPTION:	Ref# 6003 rifle				

LABEL INFORMATION

MAIL LABEL TO: Woodsbay Gunsmithing
13390 Montana Hwy 35
Big Fork, MT 59911
Ph: 406-837-1101

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 MAR 16, 2011 ALL CURR USD SVC GNDCOM ACT UT 10.0 LBS TRACKING# 1Z4XX5969066721172 1 OF 1 REF 1: WOODSBAY GUNSMITHING/SWP/DELL REF 2: REF# 6003 RIFLE HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 COD 0.00 DV 0.00 DC 0.00 SD 0.00 DGD 0.00 SP 0.00 0.00 AH 0.00 TOT PUB CHG 12.51 PR PUB+HANDL ING 12.51



