Remington Arms Co., Inc. **Product Service** Legal Case #:5710

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 4/12/2011 X 228463 4/11/2011 1/19/2011

Customer Information

Street Contact City State Zip Type Business First Name Last Name Age 95 West Monroe St H 724-288-6072 PA 15650 Incident Patrick Davis Latrobe

**Incident Information** 

Repair Medical Medical Claims Codes Est. Treatment Status

PΙ

Altered Adjustments or Cause:4006 PD Components

Unknown

Fires with side pressure on S the trigger

Unexplained Discharge Safe Concern:1006

OFF

1/19/11 Per call from Davis, he bought a Model 710 used and he stated that when he has the safety off and puts side pressure on the trigger it has fired.cm

Firearm Information

DOM Model/Ga. SKU Serial Bbl. Mfg. Type 710/30-06 4/14/2003 4:36:51 CF/BA 27410 71111227 CX Remington **SPRG** PM Original Date Where Purchased Accessories Purchased Owner WAL-MART DC 6003R-SCOPE BASE N **REGULAR** 

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Cash Reim. Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Return as received

> Repair/Replacement Repair/Replacement Cost Date

1/19/11 Mailing ARS.cm 4/15/11 Per Ilion, the trigger assm dirty, rusty and set screws altered. Old style trigger assm is no longer available. Rifle found to have an extreme max headspace condition, not repairable. Can offer to replace at 1/2 normal cost.cm 5/12/11 Sent email with quote/inspect. Will return as rec'd on 5/18 if no response.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date	,	4/12/2011

http://cps03an13:200/psaapp/PrintDisplay.aspx?ID=5710&Type=Case

5/18/2011

Examination	Product Type	1	RF
	Action Type		A
	Assigned To	1	T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		22" 3006 SPRG
	Date Code		CX
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
,	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	]
Massasina	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	]
0 11	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receive	Bulged	False	
	Description		M/710 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY.TRIG NOT RETURNING WILL FOLLOW DOWN
Trigger	Pull	Select	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	

January 19, 2011

Patrick Davis 95 West Monroe St Latrobe, PA 15650

Subject: #5710, Model 710


Dear Mr. Davis,

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the boxes with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



T.A. Snety, Rusty + set screws Altered. O/s TPA, Molongen ausil. CAN remove chand aset to within factory specs. ATI/2 NORmal costi Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Planse Return this gunto

N-DTE: Please complete and print this form, and then include it with your firearm.

	- <del>,</del>			
Model Number: 710	Serial Number: 7 1111 2 27			
Are you the original owner?: YES NO				
Name: Patrick Davis -	Date of Purchase: Jan . 6 \$ 2007			
Address (no PO Boxes): 95 Westmahrors +				
City: Latrobe	State: PA Zip: 15650			
Phone (Daytime): 724-288-6072	Fax:			
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) 7929862003@yghoo.com				
E-mail Address:				
I would like to receive future e-mail updates from Re	mington.			
Please describe your problem and date of occurrence				
941 goes off when off with out squez	safty is pushed			
off with out squez	ing the trians			
	17 1961.			
Dec. 11, 2010				
The state of the s	·			
THE PROPERTY OF THE PROPERTY O				
de de la constante de la const				
and the state of t				
500 characters left				
Ammunition Information:				
Foler 91	IImin			
- Manufacturer: Neming To'n	Type: 156 r			
Other (i.e. bullet weight/type, shot size, ron der):	· · · · · · · · · · · · · · · · · · ·			
Handload Information:	·			
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: NONC
How often do you clean the bore? (Months or Number of rounds) EVETYGMONTHS  How often do you clean the action? (Months or Number of rounds) EVETY 6 M ON THS
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds) haven't
Brand of lubricant used: VONC
How often do you lubricate the bore? (Months or Number of rounds) haven't
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?  YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it.  :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)  :: Remove all accessories from your firearm to prevent loss or damage.  :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	1/19/2011 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKAGE:		10
PLEASE CHECK ONE:			
MEDIA			
COORDINATOR	Ì	xx	
TO MAIL	I WILL MAIL		
DESCRIPTION:			
	710		
	71111227		

## LABEL INFORMATION

MAIL LABEL TO:	Patrick Davis 95 West Monroe St Latrobe, PA 15650
RETURN ITEM TO:	Rem Product Service

## PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

```
AXX59E JAN 19, 2011 ALL CURR USD 1 OF 1 SYC GNDCOM ACT UT 10.0 LBS TRACKING# 1Z4XX5969065254849
REF 1:PATRICK DAVIS/CD/CM REF 2:710/71111227

HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 DV 0.00 DGD 0.00 SD 0.00 DC 0.00 PR 0.00 SP 0.00 AH 0.00 PR 0.00 PR 0.00 TOT PUB CHG 7.94
```



