

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6142

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
229582	4/25/2011	4/26/2011	4/26/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Dave	Ailes	915 Leavey Ranch Rd	Cheyenne	WY	82007		H 307-286-4696 E dpaille4@yahoo.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired when unloading and without touching trigger	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

5/9/11 Per note with rifle, the rifle has gone off when unloading it. The rifle has also gone off without touching the trigger.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	722/257 ROBERT	n/a	317545	PZZ	6/1/1953
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/722/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at bLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.51	5/9/2011				

5/9/11 Per Ilion, could not duplicate concern. Trigger assm dirty. Can offer to replace TPA, clean, test fire at bLSM program price for \$20 + S&H.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/26/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 257 ROBERTS
	Date Code		PZZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/722 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.016
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		TWO PIECE BASE

6142

24"  
7226/53  
9#  
016

Model Number: 722		Serial Number: 317545	
Name: <del>David Ailer</del>		Date of Purchase:	
Address (no PO Boxes): 915 Leavey Ranch Road			
City: Cheyenne		State: WY	Zip: 82007
Phone (Daytime): 307-286-4696		Fax:	
E-mail Address: dpaile4@yahoo.com			
<p><b>Please describe your problem:</b></p> <p>The rifle has gone off when unloading it. The rifle has also gone off with out touching the trigger.</p> <p>400 characters left</p>			
<p><b>NOTE:</b> Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.</p> <p><input type="checkbox"/></p>			
<p>your firearm before sending it. - prevent further damage in shipping and erably, ship in a il boxes may not be returned.) ir firearm to prevent loss or damage. or UPS or Parcel Post. Remington is not damage or loss to purchase insurance from your carrier.</p> <p>Reset</p>			

David Ailer

Number:

317545

Model: 722



RE00229582

17.64

27. —

20. —

64.64

-35.13

29.51

could not duplicate concern.  
T.A. dirty. CAN offer to replace  
TPA, CLEAN + Test Rifle under  
BCL for \$20.00 + ship  
Quote

RECEIVED  
APR 27 2011

BY: .....









