Remington Arms Co., Inc. Product Service Legal Case #:6138

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 4/25/2011 4/21/2011 4/25/2011 Х 229501

Customer Information

Street Zip Business First Name Last Name City State Contact Type Age 121 Spring Valley Cir. H 719-686-1009 Dick Divide CO 80814 Incident Kyle

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ы

PD Cause:4015 Improper Maintenance S Concern: 1007 Fired on Safe Release

Unknown

C FSR

Customer sent gun in. He stated that gun fires when taken off safe. df

Firearm Information

Model/Ga. SKU DOM Mfg. Type Serial Bbl. CF/BA 788/7MM08 REM n/a B6123697 RB 11/6/1981 Remington **Date Purchased** Where Purchased

L HORTON SOUTHBOROUGH MASS

Original Owner Accessories SCOPE BASE

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/788/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

5/6/11: Per Ilion - Inside TA dirty & rusty. Trigger is frozen to side plates. Will remove, disassemble & clean TA. Send for test firing at 1/2 normal cost - quote. I spoke w/customer & he mailed appv & payment to us. Should get it next week. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/25/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		18.5" 7MM08 REM
	Date Code		RB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
			□

httn://cns03an13:200/psaann/PrintDisplay.aspx?ID=6138&Tyne=Case

5/6/2011

ı .	u	II.	
	Firing Pin	Slightly Worn; Functioning	
			=
	Shroud	Slightly Worn; Functioning	
		Slightly Worn;	
Bolt	Face	Functioning	
	11	Slightly Worn;	
	Handle	Functioning	
		Slightly Worn; Not	WAS UNABLE TO REMOVE BOLT FROM REC.
	Stop	Functioning	(FROZEN/BINDING)
	Condition	Slightly Worn; Functioning	
To do a de a		Slightly Worn;	=
Extractor	Cut Condition	Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
T a alvina	Lug Condition	Slightly Worn;	
Locking	Lug Condition	Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Not Functioning	RIFLE IS IN VERY GOOD COND
Overall	Stock Condition	Slightly Worn;	
		Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/788 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	·
Sear	Lift	Sclect	N/A
	Notch	Slightly Worn;	
	T TOTOL	Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG IS FROZEN TO SIDEPLATES
	Pull	Select	N/A
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

DICK KY/E :6138
121 Spring YALLEY CIR.
DIVIDE, CO. 80814
Phone # 719-686-1009

GUN FIRES WHER NOU TAKE THE SAFETY Off.

B6123697 Model: 788

RE00229501

()	īC	رَحَ	77	₩ 2011	
	APR	2	7	2011	
ο.	v.				

INSIDE P.A. DIRTY+RUSTY. TRIQ.
IS FROZEN to Sideplates. WILL
Remove, disassmatclear TPA.
SEND COR TEST FIREING of 1/2
NORMALLOSX.

Quote





