

Remington Arms Co., Inc. Product Service Legal Case #:6731

Case Information

Date Opened(PS) **Date Closed** RE# **Date Opened Incident Date** Pre Lit Lit Obsolete 245743 11/3/2011 10/25/2011 11/4/2011 10/22/2011

Customer Information

Street Type **Business** First Name Last Name City Contact State Zip Age #3 Orlando Dr Columbia W 860-228-1666 Reporter Center Sports Center Sports CT 06237

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern S Concern:1007 Fired on Safe Release

Unknown

C FSR

10/25/11: Jim Cummings @ store called in. He stated that consumer brought his rifle in & stated it had a FSR. No damage, No injury. df

Firearm Information

Mfg. Model/Ga. SKU Bbl. DOM Type Serial Remington CF/BA 7/7MM-08 REM 24762 S7648322 DW 9/16/2002 6:36:39 PM Original Owner

Where Purchased **Date Purchased** Accessories

JERRY S SPORT CENTER NORT SCOPE BASE U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/7/CF/BA

Reim. Date Cash Date Cash Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Repair/Replacement Cost Repair/Replacement Date

10/25/11: Mailing ARS, letter, forms. df 11/14/11: Per Ilion - Could not duplicate concern. TA very dirty & sticky. Replace TA, clean & test fire @ 1/2 normal cost - quote. I called dealer but they are closed on Monday. Faxed the quote to dealer. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/4/2011
Examination	Product Type]	RF
,	Action Type]	A
	Assigned To]	T.NAGLE
Cause	4038	Could Not Duplicate Concern	POOR MAINTENENCE
	Description		20" 7MM08 REM SS
	Date Code]	DW
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning]
	Shroud	Slightly Worn; Functioning]
	Face	Slightly Worn; Functioning]
1	1		1

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6731&Type=Case

11/14/2011

	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	· · · · · · · · · · · · · · · · · · ·
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Worn; Functioning	DID NOT CLOSE ON SAAMI OVERMAX
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description]	M/7 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	·
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	DIRTY
	Tests	Test Fired	False
Feeding Test	1 6515	False	
	Condition	Slightly Worn; Functioning	VERY DIRTY,STICKY
Tricon	Pull	Select	6#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

#Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

									.
Repair Number	Ser	ial Number / Description				Date Rec	eived:	10/25/2	2011
RE00245743	S76	548322				- Estimate	Date:	11/04/2	2011
	Mo	del 7 Center Fire Caliber: 7 MM 08 REM				Date Pri	nted:	11/14/2	2011
Customer:					n To:				
CENTER SPO	ORTS				CENTER SPOR	TS			
ATTN: JIM	0 DD				ATTN: JIM	20			
#3 ORLAND	ODR CT 06237 U	IC			¹ 3 ORLANDO I COLUMBIA, C		c		
<u></u>		J3			DOLUMBIA, C	1 00237 U	3		
Please Circle One									
VISA MC	DISCOVER				Exp	.Date			
Open Account	t: R	PO Number:							
Approval Signatu	re:	Time t				Date:			
Daytime Phone	e: ()	Time t	to Call: _						
If you desire	e any change, j	please use the reverse side for your comment	ts and ma	rk this bo	ox.				
Taki nyajnyawisa	*#####################################	TOWN OF THE OWNER, WAS ASSESSED. Pro	blems	w 100 H 1	NEW PROPERTY	aki aya	Zar, Nag	(Asig	
Reported	i Kali iku Kufer		Found	and a second	Andrew St	gill and pro	A réside les rais		
M123 - FORW.	ARD TO PRO	DUCT SERVICE FOR INSPECTION	M123	- FORW	ARD TO PRO	DUCT SERV	VICE FOR	INSPE	CTION
and a fundaging place wherein	mon who all love o link	Technician	o Comm	onto	The state of the angle of the	Olicar I victoria (b. 18.	Indonesia de la estada	California	Tara Bara Valentes
		ger assm very dirty and sticky replace trigge						240704	
could not duplicat	ie concenii.ii1g	ger ussili very unity and sticky replace trigge	i piate as	isin, cicun	and test fire at	172 Hommai C	ost.		
<u> </u>	no Americana accepto es	TIMATE (note: CO D./Chianing and Hos	alling C	hayes a	A NOT Industr	al in Alia O	idea Valler	n, a deuter	setudu es un con CATTA
Material	Type	TIMATE (note: C.O.D./Shipping and Har Description	igung C	narges at	Warranty	Qty	Price	Disc	Amount
Maccilai	Турс	Description		eeded		From Inv	11100	Disc	Amount
F305575	Part	7 X-MARK PRO TRIG ASSB - SILVER	3	1	Billable	1	94.00	50	47.00
4000114	Service	GR-SHIPPING & HANDLING (GUN RE	PAIR)	1	Billable	1	17.00	0	17.00
4000119	Service	GR-TEST		1	Billable	1	23.00	50	11.50
1									
1									
							Total:		75.50
						Est	Sales Tax:		4.53
						(Gra	nd Total:		\$80.03

TRANSMISSION VERIFICATION REPORT

TIME NAME : 11/14/2011 12:14

FAX

3365487823

TEL

SER.# : BROC0J148005

DATE,TIME FAX NO./NAME DURATION PAGE(S) RESULT MODE

11/14 12:13 18602281422 00:00:24 00:00:24 01 OK STANDARD ECM

Quotation

Remington Service

Estimating Report


★Parts and Repairs: P:800-243-9700/F:336-548-7801 ★

Madison, NC 27025-0700 www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Numb RE00245743	S	ertal Number / Description 7648322 10del 7 Center Fire Caliber: 7 MM 08 REM	А			Date Receiv Estimate Date Printe	ıte:	10/25/20 11/04/20 11/14/20	11 –	
ATTN: JIM #3 ORLAN	CENTER SPORTS CENTER SPORTS ATTN: JIM #3 ORLANDO DR #3 ORLANDO DR									
Please Circle C		CR Card NoPO Number:			COLUMBIA, C					
Daytime Ph	nonc: ()	Tim:, please use the reverse side for your commi	ic to Call:			Date:				
Reported M123 - FOR	C	ODUCT SERVICE FOR INSPECTION	Four	rd		DUCT SERVIĆ		•	TION	
	licate concern.tr	Technic igger assm very dirty and sticky replace trig STIMATE (note: C.O.D./Shipping and H Description	ger plate	assm.elear	and test fire at	1/2 normal cost				
Material F305575 4000114	Part Scrvice	7 X-MARK PRO TRIG ASSB - SILV GR-SHIPPING & HANDLING (GUN I	'ER	1 1	Billable Billable	1 9 1 1	4.00 7.00	50 0	47. 17.	00 00
4000119	Service	GR-TEST		1.	Billable	1 2	3.00	50	11.	50



October 25, 2011

Center Sports Attn: Jim #3 Orlando Dr. Columbia, CT 06237 Phone: 860-228-1666

Ref: #6731, Model 7, Serial #S7648322

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

遺S7648322

could not duplicate concern. TiA. very dinty + Sticky.

Rephase TPA, clean+ Test Rine
At 1/2 NORMAL COST

Ono PECETVE

8 Y:

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700



ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number Serial Number / Description

SR00001874

S7648322

Model 7 Center Fire

Customer:

CENTER SPORTS ATTN: JIM #3 ORLANDO DR

COLUMBIA, CT 06237 US

Email:

Date of Request:

10/25/2011

Date Printed:

10/25/2011

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:


Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 6731 - FSR



Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.) unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u> << mailto:info@remington.com>>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

(cut here)		
Mailing Label:		
3 c '1' T 1 1	•	

Arms Services SR# SR00001874 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Product Service



ARS LABEL REQUEST FORM

DATE:	10/25/2011	Service Request #	SR00001874
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	BRING LABEL TO ME

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

CENTER SPORTS ATTN: JIM #3 ORLANDO DR SR00001874 COLUMBIA, CT 06237 US Email:

Ŀ

RETURN ITEM TO:

ILN

Arms Services

4XX596 OCT 25, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM TRACKING# 1Z4XX5969067939838 REF 1:SR00001874 REF 2:CD

HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 DV 0.00 DGD 0.00 SD 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SD 0.00 TOT PUB CHG 8.15

ATTN: Product Service



