

Remington Arms Co., Inc.
Product Service
Legal Case #:6503

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
239068	8/25/2011	8/26/2011	8/26/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Tracey	Rogers	10B Hwy 15	Blue Mountain	MS	38610		H 662-512-8536

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when safety pushed off	Cause:4006 Altered Adjustments or Components Concern:1007 Fired on Safe Release	Unknown	
C				

9/8/11 Per note with rifle, gun fires when safety is pushed off without pulling the trigger. It does not happen every time. After firing and reloaded, safety will not engage.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	7/243 WIN	29541	7807776 BZ	1/27/2005 10:20:49 AM
Date Purchased	Where Purchased	Accessories	Original Owner		
	ELLETT BROTHERS INC	SCOPE,RINGS,TWO PIECE BASE	U		

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

9/8/11 Per Ilion, trigger assm dirty, rusty and set screws altered. Replace TPA, clean and test fire at 1/2 normal cost. Called Rogers and he approved repairs.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/26/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		20" 243 WIN
	Date Code		BZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	METAL DIRTY,RUSTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/7 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	Z#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE

AGVENTURE
GROW WITH CONFIDENCE

6503

20th
DZ 1/05
2nd

Gun Fires when SAFTY is pushed OFF without
pulling Trigger. (Does not Happen every Time).
After Firing and Reloaded, SAFTY will not
engage.

Tracy Rodgers

662-512-8536

Serial
Number:

7807776

Model: 7



RE00239068

TOLL FREE AT 877-974-7333 or 662-627-7060 • AgVenturemidsouth.com
Dulaneyseed.com

T.A. dirty, rusty + set screws altered.
Replace TPA, clean + test Rize +
1/2 normal cost.

Quote

RECEIVED
AUG 31 2011

BY:







