

Remington Arms Co., Inc.
Product Service
Legal Case #:6876

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
259355	2/21/2012	11/21/2011	2/22/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Thomas	Berry	18685 S. Iowa St	Muscoda	WI	53573		H 608-739-2955

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

11/21/11 Per call from Berry, he was out with the 700 this weekend and was unloading when it fired on releasing the safety. It has a bolt lock so the safety was not on. The round fired into the dirt, no injuries or damage. He has known it had this problem but thought it would call about it after the incident this weekend. It has had a light trigger pull since his Dad bought it originally new.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/25-06 REM	n/a	6324207	AT	3/1/1970
Date Purchased	Where Purchased	Accessories	Original Owner			
	"ENTRAL SALES MILWAUKEE WISC	TWO PIECE BASE	N			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at BLSM program price						
Repair/Replacement Cost	Repair/Replacement Date					
30.40	3/6/2012					

11/21/11 Mailing ARS and box.cm 3/6/12 Per Ilion, could not duplicate concern. Trigger assm dirty and sticky. Replace TPA, clean and test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/22/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 2506 REM
	Date Code		AT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	7#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

24"
AT3/70
7#
006

6876

COPY

November 21, 2011

Thomas Berry
18685 S. Iowa St
Muscoda, WI 53573

Subject: Case # 6876, Model 700, SR# 4335

Dear Mr. Berry,

Please include a copy of this letter with the firearm as well as the Service Request form.
The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the small ends of the box "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator
Phone: 800-243-9700, ext 8684
christy.mitchell@remington.com

RECEIVED
FEB 27 2012

BY:

Number:

6324207

Model: 700



RE00259355

could not dup. concern.
T.A. dirty + sticky. Replaced
TPA, clean + test fire
under SCP for 20+

Quote

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



ATTN: Product Service # 6876

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number SR00004335	Serial Number / Description 6324207 Model 700	Date of Request: 11/21/2011 Date Printed: 11/21/2011
Customer: THOMAS BERRY 18685 S IOWA ST MUSCODA, WI 53573 US Email: give to Christy	Destination: Arms Services 14 Hoeller Ave Ilion, NY 13357 US Email:	

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	---------------	----------	-------	------	--------

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:	.00
Est Sales Tax:	.00

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 BDL		Serial Number: 0324207	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: Tom Berry		Date of Purchase: 11/2011	
Address (no PO Boxes): 18685 S. Iowa St.			
City: Muscoda		State: WI	Zip: 53573
Phone (Daytime): 608-739-2955		Fax:	
E-mail Address: (If e-mail address is provided, notification of receipt and shipment will be sent) oitsutom@mehsi.com			
E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: Rifle fired round in chamber when safety was taken off to unload, i.e. rifle discharge chambered round when safety was flipped to "fire." Trigger pull is very light.			
500 characters left			
Ammunition Information:			
Manufacturer: Remington		Type: High Velocity	
Other (i.e. bullet weight/type, shot size, powder): 100-GR PTD Soft Pt Core-Lokt			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	

Firearms Care (Cleaning and Lubrication):

Brand of cleaning solution used: Hoppe's

How often do you clean the bore? (Months or Number of rounds)

How often do you clean the action? (Months or Number of rounds)

How often do you clean the trigger assembly? (Months or Number of rounds)

Brand of lubricant used:

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

☒ YES ☐ NO

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? Never

What were the services performed?)

Remington Arms Co., Inc.
Attn: Arms Service Division
14 Hoefler Avenue
Illion, NY 13357

ⓈWARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

After every use.

ARS LABEL REQUEST FORM

DATE:	11/21/2011	Service Request #	SR00004335
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelless	email address:	Christy.Mitchell@remington.com

Business:

Remington Service
PO Box 700
Madison, NC 27025-0700
www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:	THOMAS BERRY 18685 S IOWA ST MUSCODA, WI 53573 US SR00004335 Email: give to Christy
RETURN ITEM TO:	ILN Arms Services



4XX596 NOV 21, 2011 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969067769432
REF 1:SR00004335
REF 2:

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRG:
DV 0.00 COD 0.00 SVC T/P USD
DC 0.00 DGD 0.00 RS 0.50
AH 0.00 PR 0.00 SD 0.00
TOT PUB CHG 9.61 PUB+HANDLING 9.61

ATTN: Product Service # 6876







